

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------------------|-----------------------|----------|-----------|--------------------|--------------------------------|---------------|--------------------|--------------|--|----------------------|------------------|----------------------|----------------------|-------------------------|---------------|---------------------|----------|-----------------------------------|
| Roma | Roma Airport | Administration Office | 56241 | 6RP855185 | 15 Hanger Lane | 1970's (refurbished post 2000) | Craig Carlson | 24-Jul-20 | Building | Reception, main office, boardroom and amenities foyer all plasterboard walls and ceilings with non-asbestos vinyl sheet and carpet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Airport | Administration Office | 56241 | 6RP855185 | 15 Hanger Lane | 1970's (refurbished post 2000) | Craig Carlson | 24-Jul-20 | Building | Male and female amenities asbestos cement sheeting walls and ceilings throughout | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.247; R.248; R.249 |
| Roma | Roma Airport | Administration Office | 56241 | 6RP855185 | 15 Hanger Lane | 1970's (refurbished post 2000) | Craig Carlson | 24-Jul-20 | Building | Building external asbestos cement sheeting plumbing drain trap surrounds (two) for amenities vent pipes | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.250; R.251 |
| Roma | Roma Airport | Administration Office | 56241 | 6RP855185 | 15 Hanger Lane | 1970's (refurbished post 2000) | Craig Carlson | 24-Jul-20 | Building | Building external non-asbestos fibre cement sheeting artificial weatherboard cladding and non-asbestos fibre cement sheeting soffits and external ceilings | Cement based (1) | N/A | Not present (tested) | Q34076S44; Q34076S45 | No asbestos detected | N/A | N/A | N/A | R.252; R.253; R.254; R.255; R.256 |
| Roma | Roma Airport | Chemical Shed | 56246 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | All metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.223 |
| Roma | Roma Airport | Generator Shed | 56283 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Main room plasterboard walls and ceiling with asbestos cement sheeting infill panel adjacent doorway and skylight boxing | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.235; R.236 |
| Roma | Roma Airport | Generator Shed | 56283 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Main room generator asbestos textile exhaust lagging | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed friable (2) | Medium | R.237; R.238 |
| Roma | Roma Airport | Generator Shed | 56283 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Main room generator asbestos engine gaskets | Fibrous gasket (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed friable (2) | Medium | R.239 |
| Roma | Roma Airport | Generator Shed | 56283 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Fuel storage cupboard asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.240 |
| Roma | Roma Airport | Generator Shed | 56283 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Building external asbestos cement sheeting soffits and awning ceiling at east entry | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.241; R.242; R.243 |
| Roma | Roma Airport | Pump and Equip Shed | 75580 | 6RP855185 | 15 Hanger Lane | Post 2000 | Craig Carlson | 24-Jul-20 | Building | All steel and metal sheeting construction; pumps all new installation | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.245; R.246 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Office masonite walls and ceiling with vinyl asbestos tile flooring | Vinyl tiles (1) | Bonded | Confirmed | Q34076S42 | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.224 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Kitchen asbestos cement sheeting walls (Tilux) with masonite ceiling | Cement based (1) | Bonded | Confirmed | Q34076S43 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.225 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Kitchen vinyl asbestos tile flooring | Vinyl tiles (1) | Bonded | Presumed | Similar to Q34076S42 | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.226 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Amenities asbestos cement sheeting walls (Tilux) with masonite ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S43 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.227 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Amenities vinyl asbestos tile flooring | Vinyl tiles (1) | Bonded | Presumed | Similar to Q34076S42 | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.228 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Main electrical board compressed asbestos mounting panel | Insulation board (2) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.229 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Main electrical board asbestos cement sheeting fuse box internal lining | Cement based (1) | Bonded | Presumed | None taken | Chrysotile; amosite (2) | Fair (2) | Unsealed bonded (2) | Medium | R.229 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Building external asbestos cement vent pipe | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.230 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Building external asbestos cement sheeting drain trap surround at rear of kitchen | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.231 |
| Roma | Roma Airport | Storage Shed Donga | 56242 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | Building external metal sheeting roof and walls | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.232 |
| Roma | Roma Airport | Terminal Building | 56247 | 6RP855185 | 15 Hanger Lane | Post 2000 | Craig Carlson | 24-Jul-20 | Building | All new construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Airport | Tool Store | 56245 | 6RP855185 | 15 Hanger Lane | 1960's | Craig Carlson | 24-Jul-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.234 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Stage area sub-floor predominantly timber and concrete with non-asbestos fibre cement sheeting south wall | Cement based (1) | N/A | Not present (tested) | Q34076S97 | No asbestos detected | N/A | N/A | N/A | R.528 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------------------|----------------------|----------|-----------|-------------------------|------------|---------------|--------------------|------------------|---|--------------------|------------------|----------------------|-------------------------|----------------------|---------------|----------------------|----------|----------------------------|
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Rear office area and corridor asbestos cement sheeting walls and ceilings throughout | Cement based (1) | Bonded | Confirmed | Q34076S98 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.529; R.530; R.531 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Stage area asbestos cement sheeting upper wall to main hall area visible (back of sheets) on the top and side sections of the stage; this sheeting is covered with timber panelling on the hall side in areas | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Unsealed bonded (2) | Low | R.532; R.533 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Stage area asbestos cement sheeting upper infill panels on side walls (unable to fully access or inspect due to height) | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.534 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Main hall asbestos cement sheeting upper wall to stage, including on sides behind timber panelling | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.535 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Main hall asbestos cement sheeting upper infill panels above louvres in sides of hall; unable to fully access or inspect due to height | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.536 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Main hall asbestos cement sheeting ceiling infill panels surrounding pressed metal sections; unable to fully access or inspect due to height | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.537 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Level 1 rooms (three) and access stair asbestos cement sheeting walls and ceilings (ceiling present in two rooms only) | Cement based (1) | Bonded | Confirmed | Q34076S99 | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.538; R.539; R.540; R.541 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Level 1 asbestos cement sheeting wall visible on main partition to main hall (timber panel wall over on hall side) | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.540 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Front north side storeroom asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.542 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | Front south office (part of Gallery) plasterboard walls and ceiling | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | External asbestos cement sheeting soffits on rear office section of building and on main building roof section (limited access) | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.543; R.544 |
| Roma | Art Gallery and Hibernian Hall | Hibernian Hall | 60264 | 4SP212836 | 38-44 Hawthorne St | 1930's | Craig Carlson | 13-Aug-20 | Building | External asbestos cement sheeting walls and ceiling in main front entry foyer area | Cement based (1) | Bonded | Presumed | Similar to Q34076S99 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.545 |
| Roma | Art Gallery and Hibernian Hall | Library and Gallery | 60265 | 4SP212836 | 38-44 Hawthorne St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | Internal areas throughout plasterboard and non-asbestos fibre cement sheeting walls and ceilings with non-asbestos vinyl sheet and carpet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.546 |
| Roma | Art Gallery and Hibernian Hall | Library and Gallery | 60265 | 4SP212836 | 38-44 Hawthorne St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | External non-asbestos fibre cement sheeting wall cladding and soffit sheeting | Cement based (1) | N/A | Not present (tested) | Q34076S100 | No asbestos detected | N/A | N/A | N/A | R.547; R.548 |
| Roma | Colts Rest Area | Toilet Block | 60415 | 205WV1175 | 44769-44823 Warrego Hwy | 1970's | Craig Carlson | 26-Jul-20 | Public Amenities | All concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.286 |
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Main room asbestos cement sheeting ceiling throughout with asbestos cement sheeting walls and ceiling in old stove recess | Cement based (1) | Bonded | Confirmed | Q34076S108 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.603; R.604 |
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Main room asbestos cement sheeting wall panel at north end to back room | Cement based (1) | Bonded | Presumed | Similar to Q34076S108 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.605 |
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Main room asbestos backed vinyl sheet lining on two northern benches and on south bench; the vinyl has sustained minor damage | Vinyl sheeting (2) | Friable | Confirmed | Q34076S107 | Chrysotile (1) | Poor (3) | Unsealed friable (3) | Medium | R.606; R.607; R.608 |
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Back room non-asbestos vinyl sheet flooring and non-asbestos fibre cement sheeting walls and ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S109 ; Q34076S110 | No asbestos detected | N/A | N/A | N/A | R.609; R.610 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|----------------------|----------------------|----------|-----------|-----------------|-------------|---------------|--------------------|--------------|---|--------------------|------------------|--------------------------|-----------------------|----------------------|---------------|--------------------|----------|---------------------|
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Bathroom asbestos cement sheeting ceiling with masonite walls | Cement based (1) | Bonded | Presumed | Similar to Q34076S108 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.611 |
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Building external asbestos cement sheeting soffits on main building and gable end on front verandah roof structure | Cement based (1) | Bonded | Presumed | Similar to Q34076S108 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.612; R.613; R.615 |
| Roma | Girl Guides | Girl Guide Clubhouse | 55827 | 5SP103335 | 45-49 Arthur St | 1960's | Craig Carlson | 14-Aug-20 | Building | Building external asbestos cement vent pipe for amenities | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.614 |
| Roma | Girl Guides | Girl Guide Shed | 55828 | 5SP103335 | 45-49 Arthur St | 1990's | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.617 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Front room timber walls and ceiling with non-asbestos vinyl sheet flooring | Vinyl sheeting (2) | N/A | Not present (not tested) | Similar to Q34076S110 | No asbestos detected | N/A | N/A | N/A | R.618 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Kitchen asbestos cement sheeting walls and ceiling in stove recess | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.619 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Kitchen asbestos backed vinyl sheet flooring | Vinyl sheeting (2) | Friable | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed friable (2) | Medium | R.620 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Bathroom asbestos cement sheeting walls and ceiling with some wall panelling timber at random | Cement based (1) | Bonded | Confirmed | Q34076S111 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.621; R.622 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Kitchen non-asbestos mastic under sink | Fibrous felt (2) | N/A | Not present (tested) | Q34076S112 | No asbestos detected | N/A | N/A | N/A | R.623 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Building external asbestos cement sheeting artificial weatherboards on external of stove recess; main building timber walls with metal sheeting roof | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.624 |
| Roma | Girl Guides | Guide Hut | 55826 | 5SP103335 | 45-49 Arthur St | 1930's | Craig Carlson | 14-Aug-20 | Building | Building external asbestos cement sheeting plumbing drain trap surround formwork for vent pipe | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.625 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Main open area asbestos cement perforated ceiling sheeting (plasterboard non-perforated ceiling); masonite walls and non-asbestos vinyl sheet flooring. | Cement based (1) | Bonded | Confirmed | Q34076S03 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.14 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Main open asbestos cement sheeting partition wall in office to storeroom and adult toilets. | Cement based (1) | Bonded | Presumed | Q34076S03 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | No image |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Office asbestos cement perforated ceiling sheeting. Masonite walls and non-asbestos vinyl sheet flooring. | Cement based (1) | Bonded | Confirmed | Q34076S03 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.15 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Kid's toilet asbestos cement sheeting walls and outer ceiling. Inner ceiling plasterboard. | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.16 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Adult toilet asbestos cement sheeting walls. Plasterboard ceiling. | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.17 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Storeroom asbestos cement sheeting and masonite walls at random. Perforated asbestos cement sheeting ceiling. | Cement based (1) | Bonded | Confirmed | Q34076S03 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.18 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | Cleaner's room asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.19 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | External asbestos cement infill panels around glazing, doors and on building ends | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.20; R22 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | External asbestos cement sheeting soffits and external ceilings. | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.21; R22; R23 |
| Roma | Maranoa Kindergarten | Building No1 | 55795 | 13R8613 | 53 Arthur St | Late 1970's | Craig Carlson | 30-Jun-20 | Building | External asbestos cement sheeting cladding on adult toilet | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | No image |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | Main room asbestos cement sheeting front wall including in office | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.24 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------------------------|--------------------------------------|----------|--------------|------------------|-------------|---------------|--------------------|------------------|---|--------------------|------------------|--------------------------|-----------------------|----------------------|---------------|----------------------|----------|---------------------|
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | Main room asbestos cement sheeting partition to chemical store including internal lining in store room | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.25 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | Main room asbestos cement sheeting partition to toilet and storeroom including internal lining in store | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.26 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | Storeroom asbestos backed vinyl sheet flooring section. The flooring has sustained minor damage. | Vinyl sheeting (2) | Friable | Confirmed | Q34076S04 | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.27 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | External main front wall asbestos cement sheeting (profiled shadowline sheet) | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.28 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | External asbestos cement sheeting infill panels above glazing and doors | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.29 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | External asbestos cement sheeting soffits along back wall | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.30 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | External non-asbestos fibre cement sheeting stair panels to covered awning area | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.31 |
| Roma | Maranoa Kindergarten | Building No2 | 55796 | 13R8613 | 53 Arthur St | Opened 1972 | Craig Carlson | 30-Jun-20 | Building | External asbestos cement vent pipe for amenities | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Unsealed bonded (2) | Low | R.32 |
| Roma | Maranoa Kindergarten | Shade Structure No1 | 55792 | 13R8613 | 53 Arthur St | Post 2000 | Craig Carlson | 26-Jul-20 | Building | All steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.287 |
| Roma | Maranoa Kindergarten | Shade Structure No2 | 55793 | 13R8613 | 53 Arthur St | Post 2000 | Craig Carlson | 26-Jul-20 | Building | All timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.288 |
| Roma | Maranoa Kindergarten | Shade Structure No3 | 55794 | 13R8613 | 53 Arthur St | Post 2000 | Craig Carlson | 26-Jul-20 | Building | All steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.289 |
| Roma | Public Carpark - Arthur St CBD North | Parking Shade - Centre - Large | 75574 | 12RP902973 | 64 Arthur St | Post 2000 | Craig Carlson | 26-Jul-20 | Building | All steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.290 |
| Roma | Public Carpark - Arthur St CBD North | Parking Shade - South - Small | 75575 | 12RP902973 | 64 Arthur St | Post 2000 | Craig Carlson | 26-Jul-20 | Building | All steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.291 |
| Roma | Roma CBD Public Toilets | Toilet Block - Arthur Street Carpark | 56299 | Road Reserve | 136 Alice Street | Post 2000 | Craig Carlson | 26-Jul-20 | Public Amenities | Concrete block walls and metal sheeting roof with non-asbestos fibre cement sheeting upper walls and gable ends | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.292; R.293; R.294 |
| Roma | Roma Family History Lodge | Building | 76971 | 2RP64008 | 17 McDowall St | 1960's | Craig Carlson | 13-Aug-20 | Building | Main hall timber walls, floor and ceiling | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Family History Lodge | Building | 76971 | 2RP64008 | 17 McDowall St | 1960's | Craig Carlson | 13-Aug-20 | Building | Back office timber to main hall with asbestos cement sheeting remaining walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.550 |
| Roma | Roma Family History Lodge | Building | 76971 | 2RP64008 | 17 McDowall St | 1960's | Craig Carlson | 13-Aug-20 | Building | Back kitchen timber to main hall with asbestos cement sheeting remaining walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.551 |
| Roma | Roma Family History Lodge | Building | 76971 | 2RP64008 | 17 McDowall St | 1960's | Craig Carlson | 13-Aug-20 | Building | Building external asbestos cement sheeting gable ends on main building front and front verandah roof | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.552; R.553 |
| Roma | Roma Lapidary Society | Building | 62300 | 2RP64008 | 17 McDowall St | 1970's | Craig Carlson | 15-Aug-20 | Building | Main room masonry walls with non-asbestos fibre cement sheeting ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S122 | No asbestos detected | N/A | N/A | N/A | R.690 |
| Roma | Roma Lapidary Society | Building | 62300 | 2RP64008 | 17 McDowall St | 1970's | Craig Carlson | 15-Aug-20 | Building | Back storeroom asbestos cement sheeting walls to external and ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S123 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.691 |
| Roma | Roma Lapidary Society | Building | 62300 | 2RP64008 | 17 McDowall St | 1970's | Craig Carlson | 15-Aug-20 | Building | Front foyer asbestos cement sheeting wall around door to building external | Cement based (1) | Bonded | Presumed | Similar to Q34076S123 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.692 |
| Roma | Roma Lapidary Society | Building | 62300 | 2RP64008 | 17 McDowall St | 1970's | Craig Carlson | 15-Aug-20 | Building | Building external asbestos cement sheeting soffits; minor damage to timber fascia panels present | Cement based (1) | Bonded | Confirmed | Q34076S123 | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.693; R.694; R.695 |
| Roma | Roma Lapidary Society | Building | 62300 | 2RP64008 | 17 McDowall St | 1970's | Craig Carlson | 15-Aug-20 | Building | Building external non-asbestos fibre cement sheeting front access ramp flooring | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.696 |
| Roma | Roma Lawn Cemetery | Ash Wall | 26926 | 331C8110 | 2-4 Chrystal St | Post 2000 | Craig Carlson | 11-Aug-20 | Building | All brick walls with metal sheeting roof and non-asbestos fibre cement sheeting gable ends | Cement based (1) | N/A | Not present (tested) | Q34076S73 | No asbestos detected | N/A | N/A | N/A | R.402; M.403 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|---------------------------|------------------------------|----------|-----------|-----------------|-------------|---------------|--------------------|------------------|--|--------------------|------------------|--------------------------|----------------------|----------------------|---------------|---------------------|----------|---------------------|
| Roma | Roma Lawn Cemetery | Toilet Block | 60519 | 331C8110 | 2-4 Chrystal St | 1970's | Craig Carlson | 11-Aug-20 | Public Amenities | Main internal and external construction metal sheeting including adjacent mower shed | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.399 |
| Roma | Roma Lawn Cemetery | Toilet Block | 60519 | 331C8110 | 2-4 Chrystal St | 1970's | Craig Carlson | 11-Aug-20 | Public Amenities | External asbestos cement vent pipe | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Unsealed bonded (2) | Low | R.400 |
| Roma | Roma Lawn Cemetery | Toilet Block - Enviro Unisex | 55542 | 331C8110 | 2-4 Chrystal St | Post 2000 | Craig Carlson | 11-Aug-20 | Public Amenities | All timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.401 |
| Roma | Roma Monumental Cemetery | Storage Shed | 26936 | 349C844 | 2-4 Chrystal St | 1990's | Craig Carlson | 11-Aug-20 | Depot | All metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.404 |
| Roma | Roma Senior Citizens Hall | Blue Care Shed | 75582 | 4SP103335 | 51 Bungil St | Opened 1989 | Craig Carlson | 1-Jul-20 | Building | Internal foyer, front offices, staff room and upper level throughout plasterboard walls and ceilings and non-asbestos vinyl sheet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Senior Citizens Hall | Blue Care Shed | 75582 | 4SP103335 | 51 Bungil St | Opened 1989 | Craig Carlson | 1-Jul-20 | Building | Amenities areas and cleaner's room non-asbestos fibre cement sheeting walls with plasterboard ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S23 | No asbestos detected | N/A | N/A | N/A | R.137; R.138 |
| Roma | Roma Senior Citizens Hall | Blue Care Shed | 75582 | 4SP103335 | 51 Bungil St | Opened 1989 | Craig Carlson | 1-Jul-20 | Building | External non-asbestos fibre cement sheeting soffits and infill panels under glazing | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.139; R.140 |
| Roma | Roma Senior Citizens Hall | Building | 62513 | 4SP103335 | 51 Bungil St | Opened 1986 | Craig Carlson | 1-Jul-20 | Building | Internal throughout including main hall, front offices, kitchen, storerooms and amenities plasterboard walls and ceilings | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Senior Citizens Hall | Building | 62513 | 4SP103335 | 51 Bungil St | Opened 1986 | Craig Carlson | 1-Jul-20 | Building | Internal storerooms and amenities corridor non-asbestos vinyl tile flooring | Vinyl tiles (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.132 |
| Roma | Roma Senior Citizens Hall | Building | 62513 | 4SP103335 | 51 Bungil St | Opened 1986 | Craig Carlson | 1-Jul-20 | Building | Shower walls ceramic tile on suspected non-asbestos fibre cement sheeting | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.133 |
| Roma | Roma Senior Citizens Hall | Building | 62513 | 4SP103335 | 51 Bungil St | Opened 1986 | Craig Carlson | 1-Jul-20 | Building | External non-asbestos fibre cement sheeting soffits and main front awning ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S22 | No asbestos detected | N/A | N/A | N/A | R.134; R.135; R.136 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Building | Meeting area and kitchen asbestos cement sheeting ceilings | Cement based (1) | Bonded | Confirmed | Q34076S28 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.150; R.151 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Kitchen asbestos backed vinyl sheet flooring | Vinyl sheeting (2) | Friable | Confirmed | Q34076S27 | Chrysotile (1) | Fair (2) | Sealed friable (2) | Medium | R.152; R.153 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Male and female amenities asbestos cement sheeting walls and ceilings | Cement based (1) | Bonded | Presumed | Similar to Q34076S28 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.154; R.155 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Centre vehicle parking area asbestos cement sheeting upper and lower ceilings and upper walls and infill panels on sides of roller door to external | Cement based (1) | Bonded | Confirmed | Q34076S28 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.156; R.157; R.163 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Controller and communications room and equipment store asbestos cement sheeting ceilings | Cement based (1) | Bonded | Confirmed | Q34076S28 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.158; R.159 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Corridor to boat shed area (new extension; old corridor to external) | Cement based (1) | Bonded | Presumed | Similar to Q34076S28 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.160 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Level 1 non-asbestos fibre cement sheeting ceiling and timber walls | Cement based (1) | N/A | Not present (tested) | Q34076S29 | No asbestos detected | N/A | N/A | N/A | R.161 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | Level 1 access stair asbestos cement sheeting fascia panel at floor level | Cement based (1) | Bonded | Presumed | Similar to Q34076S28 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.162 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | External asbestos cement sheeting artificial weatherboard walls and asbestos cement sheeting soffits including internal within rear boat shed area (newer extension) | Cement based (1) | Bonded | Confirmed | Q34076S30 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.164; R.165; R.166 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | External asbestos cement sheeting drain trap surround adjacent entry door and for amenities | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.167 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Main Building | External suspected non-asbestos fibre cement sheeting artificial weatherboard and soffits on rear newer boat shed extension | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.168 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|----------------|----------------------------------|----------|------------|---------------|-------------|---------------|--------------------|-------------------|---|-------------------|------------------|--------------------------|----------------------|----------------------|---------------|----------------------|----------|----------------------------|
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Opened 1982 | Craig Carlson | 1-Jul-20 | Observation Tower | All steel construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.170 |
| Roma | Roma SES | SES Facility | 55822 | 11R86120 | 10-12 Whip St | Post 2000 | Craig Carlson | 1-Jul-20 | Storage Shed | All steel construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.169 |
| Roma | Student Hostel | Building - Hostel | 62525 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Internal accommodation rooms 1 - 21 all plasterboard walls and ceilings and carpet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Student Hostel | Building - Hostel | 62525 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Internal office, kitchen, dining and common areas plasterboard walls and ceilings with non-asbestos vinyl sheet flooring with limited area of non-asbestos fibre cement | Cement based (1) | N/A | Not present (tested) | Q34076S60 | No asbestos detected | N/A | N/A | N/A | R.322 |
| Roma | Student Hostel | Building - Hostel | 62525 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Internal amenities areas including staff amenities and resident amenities non-asbestos fibre cement sheeting walls and cubicle dividers | Cement based (1) | N/A | Not present (tested) | Q34076S59 | No asbestos detected | N/A | N/A | N/A | R.323; R.324; R.325 |
| Roma | Student Hostel | Building - Hostel | 62525 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Roof cavity non-asbestos fibre cement sheeting fire walls present in ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S61 | No asbestos detected | N/A | N/A | N/A | R.326; R.327 |
| Roma | Student Hostel | Building - Hostel | 62525 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Building external brick walls with non-asbestos fibre cement sheeting soffits, gable ends and infill panels above glazing | Cement based (1) | N/A | Not present (tested) | Q34076S62 | No asbestos detected | N/A | N/A | N/A | R.328; R.329; R.330 |
| Roma | Student Hostel | Building - Houseparents Cottage | 75576 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Internal lounge, kitchen, dining, bedrooms, toilet and bathroom main room all plasterboard walls and ceilings with carpet and ceramic tile flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Student Hostel | Building - Houseparents Cottage | 75576 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Internal non-asbestos fibre cement sheeting walls in bathroom shower recess and in ensuite | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S60 | No asbestos detected | N/A | N/A | N/A | R.318; R.319 |
| Roma | Student Hostel | Building - Houseparents Cottage | 75576 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Building external brick walls with non-asbestos fibre cement sheeting soffits | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S62 | No asbestos detected | N/A | N/A | N/A | R.320 |
| Roma | Student Hostel | Carport - Cottage | 62613 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.321 |
| Roma | Student Hostel | Shed - 6 Bay Garage and Store | 26968 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | Internal construction all non-asbestos fibre cement sheeting walls and ceilings including in laundry, gym and storerooms | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.313; R.314; R.315; R.316 |
| Roma | Student Hostel | Shed - 6 Bay Garage and Store | 26968 | 15SP166549 | 31 Powell St | 1990's | Craig Carlson | 27-Jul-20 | Building | External construction brick and metal sheeting roof and walls with non-asbestos fibre cement sheeting infill panels in area | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.317 |
| Roma | Student Hostel | Shed - Colorbond Single Detached | 28467 | 15SP166549 | 31 Powell St | Post 2000 | Craig Carlson | 27-Jul-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.312 |
| Roma | Student Hostel | Shelter - Outdoor Entertaining | 75577 | 15SP166549 | 31 Powell St | Post 2000 | Craig Carlson | 27-Jul-20 | Building | All steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.311 |
| Roma | The Big Rig | 01 Info Shelter - 2bay | 55811 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.627 |
| Roma | The Big Rig | 02 Info Shelter - 2bay | 55812 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.628 |
| Roma | The Big Rig | 03 Info Shelter - 3bay | 55813 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.629 |
| Roma | The Big Rig | 04 Info Shelter - 2bay | 55814 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.630 |
| Roma | The Big Rig | 05 Shed - Journey Through Time | 55807 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.631 |
| Roma | The Big Rig | 06 Info Shelter - 3bay | 55815 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.632 |
| Roma | The Big Rig | 07 Info Shelter - 1bay | 55816 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.633 |
| Roma | The Big Rig | 07 Info Shelter - 1bay | 55816 | 1CP905212 | 2 Riggers Rd | 1930's | Craig Carlson | 14-Aug-20 | Display Item | EMSCO Rig asbestos textile gaskets and friction materials suspected | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.634 |
| Roma | The Big Rig | 08 Info Shelter - 1bay | 55808 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.635 |
| Roma | The Big Rig | 08 Shelter - JPs Truck | 55806 | 1CP905212 | 2 Riggers Rd | 1940's | Craig Carlson | 14-Aug-20 | Display Item | JP's truck asbestos textile gaskets and friction materials suspected | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.636 |
| Roma | The Big Rig | 09 Info Shelter - 1side | 27192 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.637 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------------|--------------------------------|----------|-----------|-----------------|------------|---------------|--------------------|--------------|--|-------------------|------------------|--------------------------|-------------------------|----------------------|---------------|----------------------|----------|---------------------|
| Roma | The Big Rig | 09 Info Shelter - 1side | 27192 | 1CP905212 | 2 Riggers Rd | 1960's | Craig Carlson | 14-Aug-20 | Display Item | Schlumberger truck asbestos textile gaskets and friction materials suspected | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.638 |
| Roma | The Big Rig | 09 Info Shelter - 1side | 27192 | 1CP905212 | 2 Riggers Rd | 1960's | Craig Carlson | 14-Aug-20 | Display Item | T32 rig asbestos textile gaskets and friction materials suspected | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.639 |
| Roma | The Big Rig | 10 Info Shelter - 3side | 27194 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.640 |
| Roma | The Big Rig | 11 Info Shelter - 3side | 62484 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.641 |
| Roma | The Big Rig | Halliburton Truck | Unknown | 1CP905212 | 2 Riggers Rd | 1970's | Craig Carlson | 14-Aug-20 | Display Item | Truck asbestos textile gaskets and friction materials suspected including gasket materials on pipework adjacent truck | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.642; R.643; R.644 |
| Roma | The Big Rig | Steam Engine | Unknown | 1CP905212 | 2 Riggers Rd | 1920's | Craig Carlson | 14-Aug-20 | Display Item | Engine/machine asbestos textile gaskets and friction materials suspected | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.645 |
| Roma | The Big Rig | ACCO Truck | Unknown | 1CP905212 | 2 Riggers Rd | 1970's | Craig Carlson | 14-Aug-20 | Display Item | Truck asbestos textile gaskets and friction materials suspected | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed friable (3) | Medium | R.646 |
| Roma | The Big Rig | The Night Show | 63598 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All metal sheeting construction including control box with non-asbestos fibre cement sheeting walls, floor and ceiling in control box | Cement based (1) | N/A | Not present (tested) | Q34076S113 | No asbestos detected | N/A | N/A | N/A | R.647 |
| Roma | The Big Rig | Visitor Information Centre | 55800 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | Main building internal plasterboard and timber construction with non-asbestos vinyl sheet flooring; non-asbestos fibre cement sheeting walls in amenities and staff area | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S114 | No asbestos detected | N/A | N/A | N/A | R.648; R.649; R.650 |
| Roma | The Big Rig | Visitor Information Centre | 55800 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | Main building external non-asbestos fibre cement sheeting wall cladding and soffit sheeting | Cement based (1) | N/A | Not present (tested) | Q34076S114 ; Q43076S115 | No asbestos detected | N/A | N/A | N/A | R.651; R.652 |
| Roma | The Big Rig | Visitor Information Centre | 55800 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | NOGI building internal plasterboard construction with non-asbestos vinyl sheet and carpet flooring; non-asbestos fibre cement sheeting walls in amenities | Cement based (1) | N/A | Not present (tested) | Q34076S116 | No asbestos detected | N/A | N/A | N/A | R.653; R.654; R.655 |
| Roma | The Big Rig | Visitor Information Centre | 55800 | 1CP905212 | 2 Riggers Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Building | NOGI building external brick and timber walls with non-asbestos fibre cement sheeting soffits | Cement based (1) | N/A | Not present (tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.656 |
| Roma | Animal Pound (Tiffin St) | Animal Pound | 60411 | 1RP905205 | 206 Tiffin St | 1980's | Craig Carlson | 11-Aug-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.405 |
| Roma | Cartwright Street Depot | Carport | 56075 | 328WV1888 | 1 Cartwright St | 1990's | Craig Carlson | 27-Jul-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.331 |
| Roma | Cartwright Street Depot | Donga - Staff Ablution | 60382 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal all metal sandwich panel walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.332 |
| Roma | Cartwright Street Depot | Donga 01 - Lab - Microbiology | 60371 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.333 |
| Roma | Cartwright Street Depot | Donga 02 - Lab - Chemistry | 60372 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.334 |
| Roma | Cartwright Street Depot | Donga 03 - Procurement | 55916 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.335 |
| Roma | Cartwright Street Depot | Donga 04 - PL8009 | 63298 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.336 |
| Roma | Cartwright Street Depot | Donga 05 - Plant and Workshops | 60375 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.337 |
| Roma | Cartwright Street Depot | Donga 06 - (prev Plant) | 60378 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.338 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|-------------------------|--|----------|-----------|-----------------|------------|---------------|--------------------|--------------|---|------------------|------------------|--------------------------|----------------------|----------------------|---------------|---------------|----------|-----------------------------------|
| Roma | Cartwright Street Depot | Donga 07 - ERSQE | 60379 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.339 |
| Roma | Cartwright Street Depot | Donga 08 - Waste Services | 60380 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.340 |
| Roma | Cartwright Street Depot | Donga 10 - Area 10 Road | 60381 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.341 |
| Roma | Cartwright Street Depot | Donga 11 - Attached to Infrastructure Office | Unknown | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.342 |
| Roma | Cartwright Street Depot | Donga 12 - Stores Issues | 60383 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.343 |
| Roma | Cartwright Street Depot | Donga 13 - Meal Room Building - PL8007 | 62895 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.344 |
| Roma | Cartwright Street Depot | Gardeners - 3x Shelters for 6x Containers | 56078 | 328WV1888 | 1 Cartwright St | 1990's | Craig Carlson | 27-Jul-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.345 |
| Roma | Cartwright Street Depot | Infrastructure Offices and Store | 56076 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Stores area all metal sheeting walls and roof with non-asbestos fibre cement sheeting partition to east | Cement based (1) | N/A | Not present (tested) | Q34076S63 | No asbestos detected | N/A | N/A | N/A | R.346 |
| Roma | Cartwright Street Depot | Infrastructure Offices and Store | 56076 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | West end and centre offices plasterboard walls and ceiling tiles with non-asbestos vinyl sheet flooring; non-asbestos fibre cement sheeting partition to west offices in entry corridor | Cement based (1) | N/A | Not present (tested) | Q34076S64 | No asbestos detected | N/A | N/A | N/A | R.347 |
| Roma | Cartwright Street Depot | Infrastructure Offices and Store | 56076 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | East area lunch room and kitchen plasterboard and non-asbestos fibre cement sheeting walls and perforated ceiling tiles | Cement based (1) | N/A | Not present (tested) | Q34076S65 | No asbestos detected | N/A | N/A | N/A | R.348; R.349; R.350 |
| Roma | Cartwright Street Depot | Infrastructure Offices and Store | 56076 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | East area foyers and amenities areas non-asbestos vinyl tile flooring | Vinyl tiles (1) | N/A | Not present (not tested) | Similar to Q34076S68 | No asbestos detected | N/A | N/A | N/A | R.351; R.352; R.353; R.354; R.358 |
| Roma | Cartwright Street Depot | Infrastructure Offices and Store | 56076 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | East office area male and female amenities area including corridor and cleaner's room non-asbestos fibre cement sheeting ceiling tiles and laminated walls in cubicles | Cement based (1) | N/A | Not present (tested) | Q34067S66 | No asbestos detected | N/A | N/A | N/A | R.355; R.356; R.357; R.359 |
| Roma | Cartwright Street Depot | Infrastructure Offices and Store | 56076 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Building external all metal sheeting walls, roof, soffits and façade panels | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Cartwright Street Depot | Office Building (Dev Env Facilities) | 56073 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Office area and lunch room non-asbestos fibre cement sheeting ceiling tiles | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S65 | No asbestos detected | N/A | N/A | N/A | R.360; R.361; R.363; R.364 |
| Roma | Cartwright Street Depot | Office Building (Dev Env Facilities) | 56073 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Amenities corridor non-asbestos fibre cement sheeting ceiling tiles | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S65 | No asbestos detected | N/A | N/A | N/A | R.362 |
| Roma | Cartwright Street Depot | Office Building (Dev Env Facilities) | 56073 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Amenities corridor non-asbestos vinyl tile flooring in storage cupboard | Vinyl tiles (1) | N/A | Not present (not tested) | Similar to Q34076S68 | No asbestos detected | N/A | N/A | N/A | R.365 |
| Roma | Cartwright Street Depot | Office Building (Dev Env Facilities) | 56073 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Amenities laminated non-asbestos fibre cement sheeting walls in cubicles | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S71 | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Cartwright Street Depot | Office Building (Dev Env Facilities) | 56073 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Building external all metal sheeting walls, roof, soffits and façade panels | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Cartwright Street Depot | Plumbers Shed | 56079 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.366 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------------|--|----------|-----------|-----------------|-------------------------------|---------------|--------------------|--------------|--|-----------------------|------------------|--------------------------|----------------------|-------------------------|---------------|---------------------|----------|---------------------|
| Roma | Cartwright Street Depot | Shade Shelter - on North of Admin Bldg | 56081 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 27-Jul-20 | Depot | All steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.367 |
| Roma | Cartwright Street Depot | Storage Sheds - Workshop x2 - Stock Routes No3 | 56080 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.368 |
| Roma | Cartwright Street Depot | Workshop | 56077 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Office area and mezzanine lunch room non-asbestos vinyl tile flooring | Vinyl tiles (1) | N/A | Not present (tested) | Q34076S68 | No asbestos detected | N/A | N/A | N/A | R.369; R.370 |
| Roma | Cartwright Street Depot | Workshop | 56077 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Level G toilet foyer and open area adjacent to stair foyer area non-asbestos fibre cement sheeting ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S69 | No asbestos detected | N/A | N/A | N/A | R.371; R.372 |
| Roma | Cartwright Street Depot | Workshop | 56077 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Main workshop metal sheeting roof and walls with non-asbestos fibre cement sheeting upper wall to mezzanine lunch room and amenities area including upper wall in access stairwell | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S69 | No asbestos detected | N/A | N/A | N/A | R.373; R.376 |
| Roma | Cartwright Street Depot | Workshop | 56077 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Mezzanine amenities laminated non-asbestos fibre cement sheeting walls with non-asbestos fibre cement sheeting ceiling tiles | Cement based (1) | N/A | Not present (tested) | Q34076S71; Q34076S72 | No asbestos detected | N/A | N/A | N/A | R.374; R.375 |
| Roma | Cartwright Street Depot | Workshop | 56077 | 328WV1888 | 1 Cartwright St | 1980's | Craig Carlson | 27-Jul-20 | Depot | Mezzanine storage area at rear of amenities structure stored roll of asbestos gasket material and pre-cut gaskets present | Fibrous gasket (2) | Bonded | Confirmed | Q34076S70 | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.377; R.378 |
| Roma | Disaster Recovery Centre | IT Solutions Data Pod | 56295 | 328WV1888 | 1 Cartwright St | Post 2000 | Craig Carlson | 11-Aug-20 | Depot | Steel container; no asbestos present | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.406 |
| Roma | Water Tower | Gasfitters Shed | 42583 | 7SP222875 | 68-72 Bowen St | 1980's | Craig Carlson | 26-Jul-20 | Depot | Main building metal sheeting roof and walls with non-asbestos fibre cement sheeting walls and ceilings in office and toilet | Cement based (1) | N/A | Not present (tested) | Q34076S55; Q34076S56 | No asbestos detected | N/A | N/A | N/A | R.295; R.296; R.297 |
| Roma | Water Tower | Old Laboratory and Pump Room | 74991 | 7SP222875 | 68-72 Bowen St | 1960's; refurbished post 2000 | Craig Carlson | 26-Jul-20 | Depot | Internal non-asbestos fibre cement sheeting walls and ceiling in office and toilet and masonite walls and ceiling in pump room | Cement based (1) | N/A | Not present (tested) | Q34076S57 | No asbestos detected | N/A | N/A | N/A | R.299 |
| Roma | Water Tower | Old Laboratory and Pump Room | 74991 | 7SP222875 | 68-72 Bowen St | 1960's; refurbished post 2000 | Craig Carlson | 26-Jul-20 | Depot | External brick walls with non-asbestos fibre cement sheeting and masonite soffits | Cement based (1) | N/A | Not present (tested) | Q34076S58 | No asbestos detected | N/A | N/A | N/A | R.300; R.713 |
| Roma | Water Tower | Plumbers 5-Bay Shed | 60746 | 7SP222875 | 68-72 Bowen St | Post 2000 | Craig Carlson | 26-Jul-20 | Depot | Main building all steel and metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.298 |
| Roma | Neighbourhood Centre | Carport (Held for Sale) | 55917 | 1SP276517 | 29A Bowen St | 1980's | Craig Carlson | 24-Jul-20 | Building | All metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.284 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing west amenities and corridor asbestos cement sheeting walls with masonite ceilings | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.258; R.259 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing room 1 asbestos cement sheeting partition to toilet and wall around door | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.260 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing room 2 asbestos cement sheeting walls under glazing to external and single panel on wall to open area | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.261 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing open area asbestos cement sheeting panel painted as blackboard | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.262 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing throughout non-asbestos vinyl sheet and carpet flooring | Vinyl sheeting (2) | N/A | Not present (tested) | Q34076S47 | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing rooms 3, 4 and 6 non-asbestos fibre cement sheeting and plasterboard walls | Cement based (1) | N/A | Not present (tested) | Q34076S48; Q34076S49 | No asbestos detected | N/A | N/A | N/A | R.263; R.264; R.265 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing kitchen masonite main walls and ceiling with low density asbestos fibreboard infill panel above door to external, wall behind stove and infill panel next to louvres | Low density board (2) | Friable | Confirmed | Q34076S50 | Chrysotile; amosite (2) | Good (1) | Sealed friable (2) | Medium | R.266; R.267 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|-----------------------------|---------------------------------|----------|-----------|------------------|-------------|---------------|--------------------|--------------|---|------------------|------------------|--------------------------|-----------------------|-------------------------|---------------|-------------------|----------|----------------------------|
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing laundry including hot water system cupboard asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Confirmed | Q34076S51 | Chrysotile; amosite (2) | Good (1) | Sealed bonded (1) | Low | R.268 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing laundry access stairs and hot water system cupboard vinyl asbestos tile flooring | Vinyl tiles (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Low | R.269; R.270 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing toilet off laundry asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S51 | Chrysotile; amosite (2) | Good (1) | Sealed bonded (1) | Low | R.271 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | West wing back corridor and community room asbestos cement sheeting internal partition | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Low | R.272; R.273 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | East wing throughout plasterboard walls and ceilings in main areas with non-asbestos compressed fibre cement sheeting cubicle dividers in amenities | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.274 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | Building external east wing timber walls with metal sheeting roof and non-asbestos fibre cement sheeting soffits | Cement based (1) | N/A | Not present (tested) | Q34076S53 | No asbestos detected | N/A | N/A | N/A | R.275; R.276 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | Building external west wing asbestos cement sheeting soffits and external ceilings including foyers | Cement based (1) | Bonded | Confirmed | Q34076S52 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.277; R.278; R.279 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | Building external east wing asbestos cement sheeting fascia on west stair landing | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.280 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | Building external asbestos cement vent pipe adjacent reception entry | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.281 |
| Roma | Neighbourhood Centre | Council Offices (Held for Sale) | 55915 | 1SP276517 | 29A Bowen St | 1960 - 1980 | Craig Carlson | 24-Jul-20 | Building | Building external non-asbestos fibre cement sheeting rear verandah and access ramp flooring | Cement based (1) | N/A | Not present (tested) | Q34076S54 | No asbestos detected | N/A | N/A | N/A | R.282 |
| Roma | Neighbourhood Centre | Storage Shed (Held for Sale) | 55919 | 1SP276517 | 29A Bowen St | 1980's | Craig Carlson | 24-Jul-20 | Building | All metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.283 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Entry foyer area including amenities and cleaner's room all brick walls with metal panel and concrete ceilings and ceramic tile flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Roof cavity plant area throughout non-asbestos fibre cement sheeting walls; plasterboard walls and ceiling in Bio-Box | Cement based (1) | N/A | Not present (tested) | Q34076S101 | No asbestos detected | N/A | N/A | N/A | R.555; R.556; R.557 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Auditorium including stage area and backstage area all plasterboard, timber and non-asbestos fibre cement sheeting construction | Cement based (1) | N/A | Not present (tested) | Q34076S102 | No asbestos detected | N/A | N/A | N/A | R.560; R.561 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Auditorium stage area dressing rooms and amenities non-asbestos vinyl tile flooring | Vinyl tiles (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.563 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Function room plasterboard and brick walls with perforated non-asbestos fibre cement sheeting ceiling and non-asbestos fibre cement sheeting walls in kitchen | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S102 | No asbestos detected | N/A | N/A | N/A | R.562 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Office areas throughout plasterboard and timber walls with synthetic mineral fibre ceiling tiles; non-asbestos fibre cement sheeting walls in kitchen area | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S102 | No asbestos detected | N/A | N/A | N/A | R.564 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Building external non-asbestos fibre cement sheeting soffits, foyer ceilings, awning ceiling and window awnings | Cement based (1) | N/A | Not present (tested) | Q34076S104 | No asbestos detected | N/A | N/A | N/A | R.565; R.566; R.567; R.568 |
| Roma | Roma Bungil Cultural Centre | Building | 55909 | 1WV1857 | 57 Bungil St | 1986 | Craig Carlson | 13-Aug-20 | Building | Building external non-asbestos fibre cement sheeting retaining wall at surface ground level | Cement based (1) | N/A | Not present (tested) | Q34076S103 | No asbestos detected | N/A | N/A | N/A | R.569 |
| Roma | Station Street (Old Depot) | Cement Store | 56090 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Main building external metal sheeting roof and walls with asbestos cement sheeting upper wall section including capping along front of building | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.397 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|----------------------------|----------------------------|----------|-------------|-------------------|------------|---------------|--------------------|--------------|--|----------------------|------------------|----------------------|------------|----------------------|---------------|---------------------|----------|---------------------|
| Roma | Station Street (Old Depot) | Cement Store | 56090 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | External upper internal parapet lining asbestos cement sheeting | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.398 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Main area throughout asbestos cement sheeting ceiling under roof including within western store | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.381; R.382; R.383 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Main area mezzanine compressed asbestos electrical board mounting panel | Insulation board (2) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.392 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Main area mezzanine electrical board asbestos textile door seal on 'Federal' electrical box | Woven textile (2) | Friable | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed friable (2) | Medium | R.392 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Office area at front all concrete walls, floor and ceiling with asbestos cement sheeting internal partition at front of area | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.384; R.385 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Male amenities asbestos cement sheeting internal partition wall to urinal and sink, ceiling sheeting and compressed asbestos cement cubicle dividers | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.386; R.387; R.388 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Female amenities asbestos cement sheeting walls and ceiling in toilet and upper ceiling throughout | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.389; R.390 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Loading bay asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.391 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Building external asbestos cement sheeting soffits along eastern and western side | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.393; R.394 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Building external asbestos cement vent pipe on west of building for amenities | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.395 |
| Roma | Station Street (Old Depot) | Dairy Store | 56093 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Building external asbestos cement sheeting gable end on loading bay area | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.396 |
| Roma | Station Street (Old Depot) | Plumbers Shed | 56092 | 1R8650 | 18-20 Station St | 1960's | Craig Carlson | 27-Jul-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.379 |
| Roma | Station Street (Old Depot) | Store and Office | 56089 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Under refurbishment; all asbestos removed excepting asbestos cement sheeting bench backing panel in cleaner's room | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Poor (3) | Sealed bonded (1) | Low | R.380 |
| Roma | Station Street (Old Depot) | Truck Shed | 56091 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | Main building metal sheeting roof and walls with asbestos cement sheeting upper wall section including capping along front of building | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.397 |
| Roma | Station Street (Old Depot) | Truck Shed | 56091 | 1R8650 | 18-20 Station St | 1950's | Craig Carlson | 27-Jul-20 | Depot | External upper internal parapet lining asbestos cement sheeting | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.398 |
| Roma | Washdown Facility - Depot | Equipment Shed 3x3 | 68502 | 185SP154287 | 192-230 Currey St | Post 2000 | Craig Carlson | 11-Aug-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.407 |
| Roma | Washdown Facility - Depot | Pumphouse 6x3 | 64714 | 185SP154287 | 192-230 Currey St | Post 2000 | Craig Carlson | 11-Aug-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.408 |
| Roma | Bassett Park | Administration Site Office | 60532 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 12-Aug-20 | Building | Demountable internal plasterboard walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting and masonite artificial weatherboard | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.448 |
| Roma | Bassett Park | Barn and Stables | 27215 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | Barn and stables all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.579; R.580 |
| Roma | Bassett Park | Callers Stand No1 | 27228 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.585 |
| Roma | Bassett Park | Callers Stand No2 | 27229 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.598 |
| Roma | Bassett Park | Callers Stand No3 | 27230 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.599 |
| Roma | Bassett Park | Campdraft - KD Bar | 27146 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.592 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------|---|----------|-----------|---------------|------------|---------------|--------------------|------------------|--|------------------|------------------|--------------------------|----------------------|----------------------|---------------|-------------------|----------|---------------------|
| Roma | Bassett Park | Campdraft - Kimlins Bar | 27142 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.597 |
| Roma | Bassett Park | Entrance Ticket Office | 27045 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 12-Aug-20 | Building | Internal construction non-asbestos fibre cement sheeting walls with metal sandwich panel ceiling; external construction all metal sheeting | N/A | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.474; R.475 |
| Roma | Bassett Park | Grandstand | 26998 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Building | Lower south room and amenities masonite and non-asbestos fibre cement sheeting walls and metal sheet ceiling | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | Grandstand | 26998 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Building | Lower south room asbestos cement sheeting wall panel at site of old hot water system | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.501 |
| Roma | Bassett Park | Grandstand | 26998 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Building | Lower main centre room and kitchen concrete and masonite walls with metal sheeting ceiling | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | Grandstand | 26998 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Building | Lower servery non-asbestos fibre cement sheeting infill panels under servery to external | Cement based (1) | N/A | Not present (not tested) | Similar to Q34076S93 | No asbestos detected | N/A | N/A | N/A | R.502 |
| Roma | Bassett Park | Grandstand | 26998 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Building | External asbestos cement sheeting plumbing drain trap formworks adjacent female amenities, for downpipe under servery and on south end | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.503; R.504; R.505 |
| Roma | Bassett Park | Grandstand | 26998 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Building | External non-asbestos fibre cement sheeting infill panels under servery counter and under glazing along front (track) side of stand | Cement based (1) | N/A | Not present (tested) | Q34076S93 | No asbestos detected | N/A | N/A | N/A | R.506; R.507 |
| Roma | Bassett Park | Grandstand - Toilet Block - Female | 27003 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Public Amenities | All concrete and concrete block construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.508 |
| Roma | Bassett Park | Grandstand - Toilet Block - Male | 27008 | 1RP173063 | 136 McPhie St | 1970 | Craig Carlson | 12-Aug-20 | Public Amenities | All concrete and concrete block construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.509 |
| Roma | Bassett Park | Island Bar | 26990 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Open area and bar area all metal sheeting with limited areas of resin board substrate and shelving | N/A | N/A | No asbestos detected | Q34076S89 | No asbestos detected | N/A | N/A | N/A | R.494 |
| Roma | Bassett Park | Island Bar | 26990 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Back room brick and non-asbestos fibre cement sheeting internal walls | Cement based (1) | N/A | Not present (tested) | Q34076S90 | No asbestos detected | N/A | N/A | N/A | R.495 |
| Roma | Bassett Park | Island Bar | 26990 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Back area compressed asbestos cement sheeting partition walls to building external including in back section cold room foyer | Cement based (1) | Bonded | Confirmed | Q34076S91 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.496 |
| Roma | Bassett Park | Island Bar | 26990 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Non-asbestos fibre cement sheeting end walls on bar including wall lining in sink recess | Cement based (1) | N/A | Not present (tested) | Q34076S92 | No asbestos detected | N/A | N/A | N/A | R.497 |
| Roma | Bassett Park | Island Bar | 26990 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Non-asbestos fibre cement sheeting upper wall panels above display fridges in bar area | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.498; R.499 |
| Roma | Bassett Park | Island Bar | 26990 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | External asbestos cement sheeting infill panels above breezeway block walls on bar ends | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.500 |
| Roma | Bassett Park | Machinery Alley - Apex Bar | 27056 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.454 |
| Roma | Bassett Park | Machinery Alley - Shelter | 27070 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.455 |
| Roma | Bassett Park | Machinery Alley - Toilet Block - Female | 27065 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Public Amenities | Main building concrete block and metal sheeting construction; asbestos cement sheeting formwork for plumbing drain trap | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.456; R.457 |
| Roma | Bassett Park | Machinery Alley - Toilet Block - Male | 27060 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Public Amenities | All concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.458 |
| Roma | Bassett Park | Marquee | 26985 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 12-Aug-20 | Building | All steel framework with vinyl roofing | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.492 |
| Roma | Bassett Park | Marquee Stage | 26989 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.493 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level 1 members lounge plasterboard walls with canite ceiling | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------|--------------------------------|----------|-----------|---------------|------------------------------|---------------|--------------------|------------------|---|----------------------|------------------|--------------------------|----------------------|----------------------|---------------|---------------------|----------|----------------------------|
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level G betting area all metal sheeting with non-asbestos vermiculite insulation on underside of upper level | Insulation (3) | N/A | No asbestos detected | Q34076S94 | No asbestos detected | N/A | N/A | N/A | R.510; R.511 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Male jockey room metal sheeting walls and ceiling in main room with timber laminate walls in amenities | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Female jockey room metal sheeting walls and ceiling in main room with asbestos cement sheeting (tilux) walls in two showers and toilet | Cement based (1) | Bonded | Confirmed | Q34076S95 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.512; R.513 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Stewards room, secretary office and TAB office all metal sheeting walls and ceilings | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level 1 open area asbestos cement sheeting partition to amenities and west wall including in access stair | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.514; R.515 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level 1 male amenities asbestos cement sheeting walls (painted tilux) and ceiling and compressed asbestos cement sheeting cubicle dividers | Cement based (1) | Bonded | Presumed | Similar to Q34076S95 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.516; R.517; R.518; R.519 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level 1 female amenities asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.520 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level 1 official's box asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.521 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | Level 1 official's verandah asbestos cement sheeting railing lower panels to external, lining under stairwell and infill panels at doorway under stairs | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.522; R.523; R.524 |
| Roma | Bassett Park | Members Lounge and Betting | 27027 | 1RP173063 | 136 McPhie St | 1983 | Craig Carlson | 12-Aug-20 | Building | External all metal sheeting roof, façade panels and wall sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | New Stables | 27208 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.571 |
| Roma | Bassett Park | Old Stables by Barn | 27219 | 1RP173063 | 136 McPhie St | 1960's | Craig Carlson | 13-Aug-20 | Building | Main building all timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.581 |
| Roma | Bassett Park | Old Stables by Barn | 27219 | 1RP173063 | 136 McPhie St | 1960's | Craig Carlson | 13-Aug-20 | Building | North end room asbestos cement sheeting walls and ceiling; sheeting has sustained damage with broken edges sealed with paint | Cement based (1) | Bonded | Confirmed | Q34076S105 | Chrysotile (1) | Poor (3) | Sealed bonded (1) | Low | R.582; R.583 |
| Roma | Bassett Park | Old Stables by Barn | 27219 | 1RP173063 | 136 McPhie St | 1960's | Craig Carlson | 13-Aug-20 | Building | North end room compressed asbestos sheeting electrical meter mounting panel | Insulation board (2) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.584 |
| Roma | Bassett Park | Poultry Pavilion | 27072 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | Northern end all metal sheeting roof and walls | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.449 |
| Roma | Bassett Park | Poultry Pavilion | 27072 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | South end metal sheeting to external with asbestos cement sheeting internal walls throughout | Cement based (1) | Bonded | Confirmed | Q34076S84 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.450; R.451; R.452 |
| Roma | Bassett Park | Poultry Pavilion | 27072 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | Display cages non-asbestos fibre cement sheeting floor/base panels | Cement based (1) | N/A | Not present (tested) | Q34076S85 | No asbestos detected | N/A | N/A | N/A | R.453 |
| Roma | Bassett Park | Rodeo - Commentators Box | 27016 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.596 |
| Roma | Bassett Park | Rodeo - Nominations Office | 27150 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 13-Aug-20 | Building | Non-asbestos fibre cement sheeting internal walls and ceiling; metal sheeting external | Cement based (1) | N/A | Not present (tested) | Q34076S106 | No asbestos detected | N/A | N/A | N/A | R.593; R.594; R.595 |
| Roma | Bassett Park | Rodeo Campdraft - Shower Block | 56297 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Public Amenities | Demountable; internal all non-asbestos fibre cement sheeting and plasterboard; external all metal sheeting | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.587; R.588 |
| Roma | Bassett Park | Rodeo Campdraft - Toilet Block | 27155 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 13-Aug-20 | Public Amenities | Concrete block walls with asbestos cement sheeting plumbing drain trap surrounds (two) on south side | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Unsealed bonded (2) | Low | R.589; R.590; R.591 |
| Roma | Bassett Park | Sheep - Pavilion | 27087 | 1RP173063 | 136 McPhie St | 1970's (renovated post 2000) | Craig Carlson | 12-Aug-20 | Building | North end of building external all metal sheeting roof and walls | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.471 |
| Roma | Bassett Park | Sheep - Pavilion | 27087 | 1RP173063 | 136 McPhie St | 1970's (renovated post 2000) | Craig Carlson | 12-Aug-20 | Building | South end main room all metal sandwich panel construction; back stage area all non-asbestos fibre cement sheeting walls and ceiling | Cement based (1) | bonded | Not present (tested) | Q34076S86 | No asbestos detected | N/A | N/A | N/A | R.472; R.473 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------|-------------------------------------|----------|-----------|---------------|------------|---------------|--------------------|------------------|--|------------------|------------------|----------------------|------------|----------------------|---------------|---------------------|----------|---------------------------|
| Roma | Bassett Park | Sheep - Race and Exhibition | 62612 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.470 |
| Roma | Bassett Park | Shower Block (Donga) | 27117 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Public Amenities | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.600 |
| Roma | Bassett Park | Stud Cattle - Tie-Up Stalls No1 | 27111 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.468 |
| Roma | Bassett Park | Stud Cattle - Tie-Up Stalls No2 | 75594 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.469 |
| Roma | Bassett Park | Stud Cattle - Toilet Block - Female | 27125 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 12-Aug-20 | Public Amenities | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.465 |
| Roma | Bassett Park | Stud Cattle - Toilet Block - Male | 27123 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 12-Aug-20 | Public Amenities | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.466 |
| Roma | Bassett Park | Stud Cattle - Toilet Block - Unisex | 27127 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 12-Aug-20 | Public Amenities | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.467 |
| Roma | Bassett Park | Stud Cattle Stall No1 | 27107 | 1RP173063 | 136 McPhie St | 1991 | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.459 |
| Roma | Bassett Park | Stud Cattle Stall No2 | 27109 | 1RP173063 | 136 McPhie St | 1991 | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.460 |
| Roma | Bassett Park | Stud Cattle Stall No3 | 27108 | 1RP173063 | 136 McPhie St | 1991 | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.461 |
| Roma | Bassett Park | Stud Cattle Stall No4 | 27110 | 1RP173063 | 136 McPhie St | 1991 | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.462 |
| Roma | Bassett Park | Stud Cattle Stall No5 | 27174 | 1RP173063 | 136 McPhie St | 1991 | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.463 |
| Roma | Bassett Park | Stud Cattle Stall No6 | 27175 | 1RP173063 | 136 McPhie St | 1991 | Craig Carlson | 12-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.464 |
| Roma | Bassett Park | Testing Shed | 27183 | 1RP173063 | 136 McPhie St | 1990's | Craig Carlson | 13-Aug-20 | Building | External all metal sheeting construction with internal lining all metal sandwich panel | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.570 |
| Roma | Bassett Park | Tie-Up - New Stalls | 74179 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.572 |
| Roma | Bassett Park | Tie-Up and Stables | 27184 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 13-Aug-20 | Building | Main stables area all concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.573 |
| Roma | Bassett Park | Tie-Up and Stables | 27184 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 13-Aug-20 | Building | Amenities block concrete block construction with asbestos cement vent pipe in male amenities to building roof | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.577; R.578 |
| Roma | Bassett Park | Toilet Block - Donga | 27112 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Public Amenities | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.601 |
| Roma | Bassett Park | Toilet Block - Relocatable | 27181 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 13-Aug-20 | Public Amenities | All metal sandwich panel construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.602 |
| Roma | Bassett Park | Trackside Stalls No1 | 75584 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.574 |
| Roma | Bassett Park | Trackside Stalls No2 | 27200 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.575 |
| Roma | Bassett Park | Trackside Stalls No3 | 75585 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 13-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.576 |
| Roma | Bassett Park | Wool Court - Dining Hall | 26973 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Kitchen timber laminate walls with plasterboard ceiling and non-asbestos vinyl sheet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | Wool Court - Dining Hall | 26973 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Main room timber lower walls with asbestos cement sheeting upper walls which extend into the ceiling cavity on external walls; roof truss boxing in roof cavity asbestos cement sheeting at random locations | Cement based (1) | Bonded | Confirmed | Q34076S87 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.476; R.477; R.478 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|-------------------|---------------------------|----------|-----------|-------------------------|----------------------|---------------|--------------------|------------------|---|----------------------|------------------|--------------------------|----------------------|----------------------|---------------|---------------------|----------|---------------------|
| Roma | Bassett Park | Wool Court - Dining Hall | 26973 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Main room synthetic mineral fibre ceiling tiles and canite upper ceiling with asbestos cement sheeting beam boxing at ceiling level | Cement based (1) | Bonded | Confirmed | Q34076S88 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.479; R.480 |
| Roma | Bassett Park | Wool Court - Dining Hall | 26973 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | South storeroom asbestos cement sheeting internal wall and ceiling and external cladding | Cement based (1) | Bonded | Presumed | Similar to Q34076S87 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.481; R.482 |
| Roma | Bassett Park | Wool Court - Dining Hall | 26973 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Cleaner's room single asbestos cement sheeting ceiling panel present | Cement based (1) | Bonded | Presumed | Similar to Q34076S87 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.483 |
| Roma | Bassett Park | Wool Court - Dining Hall | 26973 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Building | Building external asbestos cement sheeting soffits and ceilings including on verandah's and in kitchen loading bay area | Cement based (1) | Bonded | Presumed | Similar to Q34076S87 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.484; R.485 |
| Roma | Bassett Park | Wool Court - Toilet Block | 26983 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Public Amenities | Internal unisex and female amenities area asbestos cement sheeting ceilings | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.486; R.487; R.488 |
| Roma | Bassett Park | Wool Court - Toilet Block | 26983 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Public Amenities | Internal cubicle dividers non-asbestos compressed fibre cement sheeting | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.489 |
| Roma | Bassett Park | Wool Court - Toilet Block | 26983 | 1RP173063 | 136 McPhie St | 1980's | Craig Carlson | 12-Aug-20 | Public Amenities | External asbestos cement sheeting soffits and external ceilings | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.490; R.491 |
| Roma | Bassett Park | Wool Pavilion | 27078 | 1RP173063 | 136 McPhie St | Refer Sheep Pavilion | Craig Carlson | 12-Aug-20 | Building | Refer Sheep Pavilion | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Bassett Park | Workshop | 27100 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 12-Aug-20 | Depot | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.447 |
| Roma | Bassett Park | Yards Feed Store | 27207 | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 13-Aug-20 | Building | All timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.586 |
| Roma | Bassett Park | Lighting Towers | Unknown | 1RP173063 | 136 McPhie St | 1970's | Craig Carlson | 12-Aug-20 | Building | Electrical boards at the base of the lighting towers were predominantly locked, with limited access. Inspection of the accessible towers revealed the electrical panels to be asbestos boards. It is suspected that all original lighting tower electrical boards would be asbestos | Insulation board (2) | Bonded | Confirmed | Q34076S96 | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.525; R.526; R.527 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Roof cavity throughout damaged asbestos cement roof sheeting as a result of incomplete asbestos roof removal and decontamination | Cement based (1) | Bonded | Confirmed | Q34076S31 | Chrysotile (1) | Poor (3) | Unsealed bonded (2) | Medium | R.171 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Front south room asbestos cement sheeting ceiling | Cement based (1) | Bonded | Confirmed | Q34076S32 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.172 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Front centre room asbestos cement sheeting internal walls and ceiling; masonite walls to external | Cement based (1) | Bonded | Presumed | Similar to Q34076S32 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.173 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Trophy room asbestos cement sheeting internal walls and ceiling; masonite walls to external | Cement based (1) | Bonded | Presumed | Similar to Q34076S32 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.174 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Kitchen asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S32 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.175 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Storeroom asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S32 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.176 |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Back room no access gained; suspected asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S32 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | No image |
| Roma | Colts Cricket | Colts Cricket Clubhouse | 28136 | 205WV1175 | 44769-44823 Warrego Hwy | 1960's | Craig Carlson | 4-Jul-20 | Building | Building external asbestos cement sheeting debris on surface ground at very low levels as a result of incomplete asbestos roof removal and decontamination | Cement based (1) | Bonded | Presumed | Similar to Q34076S31 | Chrysotile (1) | Poor (3) | Unsealed bonded (2) | Medium | R.177 |
| Roma | Disc Golf Grounds | Information Shelter | 55989 | 360R8623 | 26 Bungil St | Post 2000 | Craig Carlson | 26-Jul-20 | Park | All timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.301 |
| Roma | Disc Golf Grounds | Picnic Shelter No1 | 55990 | 360R8623 | 26 Bungil St | Post 2000 | Craig Carlson | 26-Jul-20 | Park | All timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.302 |
| Roma | Disc Golf Grounds | Picnic Shelter No2 | 55991 | 360R8623 | 26 Bungil St | Post 2000 | Craig Carlson | 26-Jul-20 | Park | All timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.303 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|---------------------------------|---------------------|----------|-------------|-------------------------|---------------------|---------------|--------------------|--------------|--|------------------|------------------|----------------------|----------------------|-------------------------|---------------|-------------------|----------|--|
| Roma | District Bowmen | Shelter | 28182 | 508WV835101 | 1702 Carnarvon Hwy | 1990's | Craig Carlson | 26-Jul-20 | Park | All timber and steel construction; roof removed | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.306 |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Wash up room and cold room area at rear of bar asbestos cement sheeting ceiling, partition to bar and infill panel at coldroom | Cement based (1) | Bonded | Presumed | Similar to Q34076S35 | Chrysotile; amosite (2) | Good (1) | Sealed bonded (1) | Low | R.178; R.179; R.180 |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Wash up room and cold room area at rear of bar vinyl asbestos tile flooring under vinyl sheet and exposed in limited areas | Vinyl tiles (1) | Bonded | Confirmed | | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.181 |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Main hall asbestos cement sheeting ceiling and partition wall from bar to wash room | Cement based (1) | Bonded | Confirmed | Q34076S35 | Chrysotile; amosite (2) | Good (1) | Sealed bonded (1) | Low | R.182; R.183 |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Amenities areas asbestos cement sheeting ceiling throughout | Cement based (1) | Bonded | Presumed | Similar to Q34076S35 | Chrysotile; amosite (2) | Good (1) | Sealed bonded (1) | Low | R.184; R.185 |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Amenities flooring ceramic tile on non-asbestos fibre cement sheeting substrate | Cement based (1) | N/A | Not present (tested) | Q34076S36 | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Lower level all concrete block and timber construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Building external asbestos cement sheeting gable end on building northern end | Cement based (1) | Bonded | Presumed | Similar to Q34076S35 | Chrysotile; amosite (2) | Good (1) | Sealed bonded (1) | Low | R.186 |
| Roma | Gallas Fox Grounds | Echidnas Clubhouse | 28145 | 205WV1175 | 44769-44823 Warrego Hwy | 1952; moved in 1997 | Craig Carlson | 4-Jul-20 | Building | Building external non-asbestos fibre cement sheeting fascia at verandah floor level | Cement based (1) | N/A | Not present (tested) | Q34076S37 | No asbestos detected | N/A | N/A | N/A | R.187 |
| Roma | Ironbark Raceway | Large Shelters | 28207 | 5SP230317 | Kimblar Road | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.657 |
| Roma | Ironbark Raceway | Medium Shelters x 2 | 28208 | 5SP230317 | Kimblar Road | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel, metal sheeting and shade cloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.658 |
| Roma | Ironbark Raceway | Medium Shelters x 4 | 28206 | 5SP230317 | Kimblar Road | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel, metal sheeting and shade cloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.658 |
| Roma | Ironbark Raceway | Vehicle Shed | Unknown | 5SP230317 | Kimblar Road | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.660 |
| Roma | Ironbark Raceway | Small Shelters x 10 | 28205 | 5SP230317 | Kimblar Road | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.659 |
| Roma | Ironbark Raceway | Toilet Block | 28197 | 5SP230317 | Kimblar Road | Post 2000 | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.661 |
| Roma | Ironbark Raceway | Canteen Building | Unknown | 5SP230317 | Kimblar Road | 1980's | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.662 |
| Roma | Ironbark Raceway | Bar | Unknown | 5SP230317 | Kimblar Road | 1980's | Craig Carlson | 14-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.663 |
| Roma | Ironbark Raceway | Control Building | Unknown | 5SP230317 | Kimblar Road | 1980's | Craig Carlson | 14-Aug-20 | Building | Internal non-asbestos fibre cement sheeting and masonite walls and ceilings throughout with non-asbestos vinyl sheet flooring | Cement based (1) | N/A | Not present (tested) | Q34076S117 | No asbestos detected | N/A | N/A | N/A | R.664; R.665; R.666; R.667; R.668; R.669 |
| Roma | Ironbark Raceway | Control Building | Unknown | 5SP230317 | Kimblar Road | 1980's | Craig Carlson | 14-Aug-20 | Building | External non-asbestos fibre cement sheeting artificial weatherboard and timber walls with metal sheeting roof | Cement based (1) | N/A | Not present (tested) | Q34076S118 | No asbestos detected | N/A | N/A | N/A | R.670 |
| Roma | Little Athletics | Storage Shed | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.414 |
| Roma | Little Athletics | Clubhouse | 28158 | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Internal masonite and non-asbestos fibre cement sheeting walls and ceilings | Cement based (1) | N/A | Not present (tested) | Q34076S76 | No asbestos detected | N/A | N/A | N/A | R.415 |
| Roma | Little Athletics | Clubhouse | 28158 | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | External masonite artificial weatherboard walls with asbestos cement sheeting soffits | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.416 |
| Roma | Roma Bungil Recreational Centre | Building - PCYC | 28169 | 5SP103335 | 45-49 Arthur St | Opened 1996 | Craig Carlson | 1-Jul-20 | Building | Internal front office and staff amenities areas plasterboard and non-asbestos fibre cement sheeting throughout | Cement based (1) | N/A | Not present (tested) | Q34076S14; Q34076S16 | No asbestos detected | N/A | N/A | N/A | R.114; R.115; R.116 |
| Roma | Roma Bungil Recreational Centre | Building - PCYC | 28169 | 5SP103335 | 45-49 Arthur St | Opened 1996 | Craig Carlson | 1-Jul-20 | Building | Internal front gym, rear gym, main hall, martial arts room plasterboard and non-asbestos fibre cement sheeting throughout | Cement based (1) | N/A | Not present (tested) | Q34076S15 | No asbestos detected | N/A | N/A | N/A | R.117; R.118; R.119; R.122; R.123 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|---------------------------------|---|----------|-----------|---------------------|-------------|---------------|--------------------|---------------|--|------------------|------------------|--------------------------|----------------------|----------------------|---------------|---------------------|----------|--------------|
| Roma | Roma Bungil Recreational Centre | Building - PCYC | 28169 | 5SP103335 | 45-49 Arthur St | Opened 1996 | Craig Carlson | 1-Jul-20 | Building | Public amenities areas at rear including back areas and corridors non-asbestos fibre cement sheeting throughout | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.120; R.121 |
| Roma | Roma Bungil Recreational Centre | Building - PCYC | 28169 | 5SP103335 | 45-49 Arthur St | Opened 1996 | Craig Carlson | 1-Jul-20 | Building | Upper level office and common areas plasterboard and non-asbestos fibre cement sheeting construction | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.124 |
| Roma | Roma Bungil Recreational Centre | Building - PCYC | 28169 | 5SP103335 | 45-49 Arthur St | Opened 1996 | Craig Carlson | 1-Jul-20 | Building | Building external non-asbestos fibre cement sheeting external cladding, soffit sheeting, fascia panels and window awnings | Cement based (1) | N/A | Not present (tested) | Q34076S17; Q34076S18 | No asbestos detected | N/A | N/A | N/A | R.125; R.126 |
| Roma | Roma Community Garden | Storage Sheds (two) | Unknown | 4R86106 | 85-91 Bowen St | Post 2000 | Craig Carlson | 26-Jul-20 | Building | All steel construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.309; R.310 |
| Roma | Roma Community Garden | Shelter | 28236 | 4R86106 | 85-91 Bowen St | Post 2000 | Craig Carlson | 26-Jul-20 | Park | All steel construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.308 |
| Roma | Roma Community Garden | Toilet Block | 28223 | 4R86106 | 85-91 Bowen St | Post 2000 | Craig Carlson | 26-Jul-20 | Park | All plastic construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.307 |
| Roma | Roma Swimming Pool | Chemical Storage Shed - Small | 60565 | 30R8610 | 136-142 McDowall St | Post 2000 | Craig Carlson | 30-Jun-20 | Swimming Pool | Structure all metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.35 |
| Roma | Roma Swimming Pool | Garden Shed No1 - Mowers, Equip | 70063 | 30R8610 | 136-142 McDowall St | Post 2000 | Craig Carlson | 30-Jun-20 | Swimming Pool | Structure all metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.36 |
| Roma | Roma Swimming Pool | Garden Shed No2 - Swim Tools and Spares | 70064 | 30R8610 | 136-142 McDowall St | Post 2000 | Craig Carlson | 30-Jun-20 | Swimming Pool | Structure all metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.37 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | East end kitchen and club house area all plasterboard and brick with non-asbestos flooring. Non-asbestos fibre cement sheeting servery at base of roller door. | Cement based (1) | N/A | No asbestos detected | Q34076S06 | No asbestos detected | N/A | N/A | N/A | R.42 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Female change room asbestos cement sheeting ceiling including skylight boxing. Brick walls and non-asbestos resin flooring. | Cement based (1) | Bonded | Confirmed | Q34076S07 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.43 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Male change room asbestos cement sheeting ceiling including skylight boxing. Brick walls and resin flooring. | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.44; R.45 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Equipment store asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.46 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Entry foyer asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.47 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Kiosk asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.48 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Kiosk counter asbestos cement sheeting ceramic tile substrate | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.49; R.50 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Stock room asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.51 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | Store room asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.52 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | External asbestos cement sheeting fascia along inner wall in front of change rooms and kiosk areas | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.53 |
| Roma | Roma Swimming Pool | Kiosk and Clubhouse | 55984 | 30R8610 | 136-142 McDowall St | Opened 1977 | Craig Carlson | 30-Jun-20 | Swimming Pool | External asbestos cement sheeting front entry foyer ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.54 |
| Roma | Roma Swimming Pool | Learners Pool - Cover | 62550 | 30R8610 | 136-142 McDowall St | N/A | Craig Carlson | 30-Jun-20 | Swimming Pool | Pool and cover removed | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------|---------------------------|----------|----------|---------------------|--------------------------|---------------|--------------------|------------------|---|-----------------------|------------------|--------------------------|----------------------|-------------------------|---------------|--------------------|----------|----------------------------|
| Roma | Roma Swimming Pool | Main Pool - Cover | 62549 | 30R8610 | 136-142 McDowall St | Post 2000 | Craig Carlson | 30-Jun-20 | Swimming Pool | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.34 |
| Roma | Roma Swimming Pool | Main Pool - Pump Shed | 55986 | 30R8610 | 136-142 McDowall St | 1990's | Craig Carlson | 30-Jun-20 | Swimming Pool | Concrete block and non-asbestos fibre cement sheeting external walls and internal walls and ceilings | Cement based (1) | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.38; R.39; R.40; R.41 |
| Roma | Roma Swimming Pool | Shelter - Viewing Seating | 62607 | 30R8610 | 136-142 McDowall St | Post 2000 | Craig Carlson | 30-Jun-20 | Swimming Pool | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.33 |
| Roma | Soccer Club | Soccer Club Building | Unknown | 82R8614 | 12-20 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | North store room and amenities all concrete block walls with metal sheeting roof | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Soccer Club | Soccer Club Building | Unknown | 82R8614 | 12-20 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Main room concrete block and non-asbestos fibre cement sheeting walls | Cement based (1) | N/A | Not present (not tested) | Q34076S75 | No asbestos detected | N/A | N/A | N/A | R.409; R.410 |
| Roma | Soccer Club | Soccer Club Building | Unknown | 82R8614 | 12-20 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Main room asbestos cement sheeting ceiling | Cement based (1) | Bonded | Confirmed | Q34076S74 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.411; R.412 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | Internal areas throughout asbestos cement sheeting ceiling including south room, centre store, kitchen and north room | Cement based (1) | Bonded | Confirmed | Q34076S77 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.417; R.418; R.419; R.420 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | Internal asbestos cement sheeting partition between two centre storerooms | Cement based (1) | Bonded | Confirmed | Q34076S80 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.421 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | Amenities non-asbestos fibre cement sheeting walls and ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S78 | No asbestos detected | N/A | N/A | N/A | R.422 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | External verandah asbestos cement sheeting ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S77 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.423 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | External verandah non-asbestos fibre cement sheeting walls panels (along with masonite also) | Cement based (1) | N/A | Not present (tested) | Q34076S79 | No asbestos detected | N/A | N/A | N/A | R.424 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | External asbestos cement sheeting wall panels on verandah | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.425 |
| Roma | Soccer Club | Clubhouse | 28106 | 82R8614 | 12-20 Bungil St | 1971 (relocated in 1990) | Craig Carlson | 11-Aug-20 | Building | External asbestos cement sheeting soffits and north gable end | Cement based (1) | Bonded | Presumed | Similar to Q34076S77 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.426; R.428; R.429 |
| Roma | Soccer Club | Toilet Block | 28107 | 82R8614 | 12-20 Bungil St | 1980's | Craig Carlson | 11-Aug-20 | Public Amenities | Concrete block walls with metal sheeting roof and concrete flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.413 |
| Roma | Touch Football | Toilet Block | 28120 | 91R8614 | 6-10 Bungil St | 1990's | Craig Carlson | 11-Aug-20 | Public Amenities | Internal concrete block walls with non-asbestos fibre cement sheeting partition at urinal | Cement based (1) | N/A | Not present (tested) | Q34076S81 | No asbestos detected | N/A | N/A | N/A | R.430 |
| Roma | Touch Football | Toilet Block | 28120 | 91R8614 | 6-10 Bungil St | 1990's | Craig Carlson | 11-Aug-20 | Public Amenities | External concrete block walls with metal sheeting roof and masonite artificial weatherboard gable ends | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.431 |
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Canteen low density asbestos fibreboard walls and ceiling with random wall panels replaced | Low density board (2) | Friable | Confirmed | Q34076S82 | Chrysotile; amosite (2) | Fair (2) | Sealed friable (2) | Medium | R.432; R.433 |
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Main room and main room northern end low density asbestos fibreboard walls and ceiling with random wall panels replaced | Low density board (2) | Friable | Confirmed | Q34076S83 | Chrysotile; amosite (2) | Fair (2) | Sealed friable (2) | Medium | R.434; R.435 |
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Equipment store low density asbestos fibreboard walls and ceiling with random wall panels replaced | Low density board (2) | Friable | Confirmed | Similar to Q34076S82 | Chrysotile; amosite (2) | Fair (2) | Sealed friable (2) | Medium | R.436; R.437; R.438 |
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Northern room low density asbestos fibreboard walls and ceiling with random wall panels replaced | Low density board (2) | Friable | Confirmed | Similar to Q34076S82 | Chrysotile; amosite (2) | Fair (2) | Sealed friable (2) | Medium | R.439 |
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Front verandah asbestos cement sheeting ceiling and infill panel above glazing | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.440; R.441 |
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Building external asbestos cement sheeting soffits including along front verandah | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.442; R.443 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|------------------------------------|------------------------------|----------|--------------|-----------------------------|---------------|---------------|--------------------|------------------|--|------------------|------------------|--------------------------|----------------------|----------------------|---------------|-------------------|----------|------------------------|
| Roma | Touch Football | Clubhouse | Unknown | 91R8614 | 6-10 Bungil St | 1970's | Craig Carlson | 11-Aug-20 | Building | Building external asbestos cement sheeting infill panels under glazing | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.444; R.445 |
| Roma | Apex Park | Farmers Cart Shelter | 27957 | 314WV1584 | 1-11 Quintin St | 1990's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.55 |
| Roma | Apex Park | Play Shelter | 27950 | 314WV1584 | 1-11 Quintin St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.57 |
| Roma | Apex Park | Small Shelter | 27956 | 314WV1584 | 1-11 Quintin St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.56 |
| Roma | Apex Park | Toilet Block | 27943 | 314WV1584 | 1-11 Quintin St | 1970's | Craig Carlson | 30-Jun-20 | Public Amenities | Concrete block walls with timber soffits and metal sheeting roof | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.58 |
| Roma | Big Rig Parkland | BBQ Picnic Table Shelter No1 | 28078 | 210WV1624 | 1 Bowen St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.59 |
| Roma | Big Rig Parkland | BBQ Picnic Table Shelter No2 | 28079 | 210WV1624 | 1 Bowen St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.60 |
| Roma | Big Rig Parkland | Boat Shelter | 28081 | 210WV1624 | 1 Bowen St | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.61 |
| Roma | Big Rig Parkland | Mini Train Shed | 55797 | 210WV1624 | 1 Bowen St | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.62 |
| Roma | Big Rig Parkland | Picnic Rotunda | 28080 | 210WV1624 | 1 Bowen St | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all timber and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.63 |
| Roma | Big Rig Parkland | Play Shelter | 28061 | 210WV1624 | 1 Bowen St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.64 |
| Roma | Big Rig Parkland | Slab Hut | 28059 | 210WV1624 | 1 Bowen St | Moved in 1980 | Craig Carlson | 30-Jun-20 | Park | Timber walls with internal ceilings asbestos cement sheeting | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.65; R.66; R.67; R.68 |
| Roma | Big Rig Parkland | Toilet Block | 28055 | 210WV1624 | 1 Bowen St | Post 2000 | Craig Carlson | 30-Jun-20 | Public Amenities | Concrete block and non-asbestos fibre cement sheeting external walls, internal ceilings and dividers | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.69; R.70; R.71 |
| Roma | Bus Shelter - Arthur Street | Bus Shelter - Arthur Street | 63138 | Road Reserve | 88 Arthur St | Post 2000 | Craig Carlson | 30-Jun-20 | Building | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.72 |
| Roma | Lions Park | Play Shelter | 27921 | Road Reserve | Third Av - NW cnr Annandale | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.73 |
| Roma | Lions Park | Play Shelter | 75579 | Road Reserve | Third Av - NW cnr Annandale | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.74 |
| Roma | Lions Park | Stage Shelter | 27934 | Road Reserve | Third Av - NW cnr Annandale | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.75 |
| Roma | Lions Park | Table Shelter No2 | 56038 | Road Reserve | Third Av - NW cnr Annandale | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.76 |
| Roma | Lions Park | Table Shelter No3 | 56039 | Road Reserve | Third Av - NW cnr Annandale | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.77 |
| Roma | Lions Park | Tables Shelter No1 | 27933 | Road Reserve | Third Av - NW cnr Annandale | 1980's | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.78 |
| Roma | Lions Park | Toilet Block | 27918 | Road Reserve | Third Av - NW cnr Annandale | Post 2000 | Craig Carlson | 30-Jun-20 | Public Amenities | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.79 |
| Roma | Queens Park and Cenotaph | Shade Structures | 60600 | 2WV1857 | 55 Bungil St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.80 |
| Roma | Roma Youth Precinct and Skate Park | Shade Shelter | 60461 | 3I71817 | 41-45 Hutton St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and shadecloth construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.81; R.82; R.83 |
| Roma | Rotary Southside Park | Picnic Shelter - New | 77747 | 99RP30933 | 18-20 Twine St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.84 |
| Roma | Rotary Southside Park | Table Shelter | 28048 | 99RP30933 | 18-20 Twine St | Post 2000 | Craig Carlson | 30-Jun-20 | Park | Structure all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.85 |
| Roma | 107 Miscamble Street | Dwelling | 28993 | 7RP128363 | 107 Miscamble St | Early 1990's | Craig Carlson | 1-Jul-20 | Building | Internal throughout plasterboard walls and ceilings in lounge, kitchen, dining, hall and bedrooms with non-asbestos vinyl sheet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 107 Miscamble Street | Dwelling | 28993 | 7RP128363 | 107 Miscamble St | Early 1990's | Craig Carlson | 1-Jul-20 | Building | Bathroom and selected areas of laundry non-asbestos fibre cement sheeting walls | Cement based (1) | N/A | Not present (tested) | Q34076S12 | No asbestos detected | N/A | N/A | N/A | R.109; R.110 |
| Roma | 107 Miscamble Street | Dwelling | 28993 | 7RP128363 | 107 Miscamble St | Early 1990's | Craig Carlson | 1-Jul-20 | Building | Building external non-asbestos fibre cement sheeting external artificial weatherboard cladding and soffit sheeting | Cement based (1) | N/A | Not present (tested) | Q34076S13 | No asbestos detected | N/A | N/A | N/A | R.111; R.112; R.113 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | Lounge room asbestos cement wall and ceiling sheeting | Cement based (1) | Bonded | Presumed | Similar to Q34076S09 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.90 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|--------------------|---------------------------------|----------|------------|--------------------|--------------|---------------|--------------------|--------------|---|--------------------|------------------|--------------------------|----------------------|----------------------|---------------|--------------------|----------|---------------------|
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | Kitchen asbestos cement wall and ceiling sheeting | Cement based (1) | Bonded | Presumed | Similar to Q34076S09 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.91 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | Kitchen asbestos backed vinyl sheet flooring | Vinyl sheeting (2) | Friable | Confirmed | Q34076S08 | Chrysotile (1) | Fair (2) | Sealed friable (2) | Medium | R.92; R.93 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | Laundry asbestos cement wall and ceiling sheeting and laminated asbestos cement sheeting (tilux) sink splashback | Cement based (1) | Bonded | Presumed | Similar to Q34076S09 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.94; R.95 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | Bedrooms (three) and centre hallway asbestos cement wall and ceiling sheeting | Cement based (1) | Bonded | Presumed | Similar to Q34076S09 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.96 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | Bathroom and toilet asbestos cement wall and ceiling sheeting | Cement based (1) | Bonded | Confirmed | Q34076S09 | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.97; R.98 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | External front verandah asbestos cement ceiling sheeting | Cement based (1) | Bonded | Presumed | Similar to Q34076S09 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.99 |
| Roma | 14 South Street | Dwelling | 29040 | 2SP179588 | 14 South St | Early 1980's | Craig Carlson | 1-Jul-20 | Building | External asbestos cement sheeting artificial weatherboard walls and asbestos cement sheeting soffits | Cement based (1) | Bonded | Confirmed | Q34076S10 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.100, R.101 |
| Roma | 3 - 5 Beitz Street | Dwelling Tower View Units 1 - 5 | 28906 | 26R8693 | 3 - 5 Beitz Street | 1993 | Craig Carlson | 30-Jun-20 | Building | All units internal lounge, kitchen, dining, bedrooms and hallway construction plasterboard walls and ceilings with non-asbestos flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 3 - 5 Beitz Street | Dwelling Tower View Units 1 - 5 | 28906 | 26R8693 | 3 - 5 Beitz Street | 1993 | Craig Carlson | 30-Jun-20 | Building | All units internal laundry and bathrooms non-asbestos fibre cement sheeting walls and plasterboard ceilings | Cement based (1) | N/A | No asbestos detected | Q34076S01 | No asbestos detected | N/A | N/A | N/A | R.04; R.05; R.06 |
| Roma | 3 - 5 Beitz Street | Dwelling Tower View Units 1 - 5 | 28906 | 26R8693 | 3 - 5 Beitz Street | 1993 | Craig Carlson | 30-Jun-20 | Building | External brick walls, metal sheet roof, non-asbestos fibre cement sheeting soffits and infill panels | Cement based (1) | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.07; R.08 |
| Roma | 7 Beitz Street | Dwelling | 28985 | 28R8693 | 7 Beitz St | 1994 | Craig Carlson | 1-Jul-20 | Building | Internal lounge, kitchen, dining, bedrooms, toilet and hallway construction plasterboard walls and ceilings with non-asbestos flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 7 Beitz Street | Dwelling | 28985 | 28R8693 | 7 Beitz St | 1994 | Craig Carlson | 1-Jul-20 | Building | Internal laundry and bathrooms non-asbestos fibre cement sheeting walls and plasterboard ceilings | Cement based (1) | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 7 Beitz Street | Dwelling | 28985 | 28R8693 | 7 Beitz St | 1994 | Craig Carlson | 1-Jul-20 | Building | External brick walls, metal sheet roof, non-asbestos fibre cement sheeting soffits and infill panels | Cement based (1) | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.86 |
| Roma | 7 Elmer Street | Dwelling | 28997 | 58RP128364 | 7 Elmer St | Early 1990's | Craig Carlson | 1-Jul-20 | Building | Internal throughout plasterboard walls and ceilings in lounge, kitchen, dining, hall and bedrooms with non-asbestos vinyl sheet and carpet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 7 Elmer Street | Dwelling | 28997 | 58RP128364 | 7 Elmer St | Early 1990's | Craig Carlson | 1-Jul-20 | Building | Bathroom and selected areas of laundry asbestos cement sheeting walls | Cement based (1) | N/A | Not present (tested) | Q34076S20 | No asbestos detected | N/A | N/A | N/A | R.127; R.128 |
| Roma | 7 Elmer Street | Dwelling | 28997 | 58RP128364 | 7 Elmer St | Early 1990's | Craig Carlson | 1-Jul-20 | Building | Building external non-asbestos fibre cement sheeting external artificial weatherboard cladding, front verandah fascia and soffit sheeting | Cement based (1) | N/A | Not present (tested) | Q34076S19; Q34076S21 | No asbestos detected | N/A | N/A | N/A | R.129; R.130; R.131 |
| Roma | 7 Whip Street | Dwelling Duplex 7-7a | 28979 | | 7 Whip Street | 1990's | Craig Carlson | 30-Jun-20 | Building | 7 and 7a internal lounge, kitchen, dining, bedrooms and hallway construction plasterboard walls and ceilings with non-asbestos flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 7 Whip Street | Dwelling Duplex 7-7a | 28979 | | 7 Whip Street | 1990's | Craig Carlson | 30-Jun-20 | Building | All units internal laundry and bathrooms non-asbestos fibre cement sheeting walls and plasterboard ceilings | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.09; R.10 |
| Roma | 7 Whip Street | Dwelling Duplex 7-7a | 28979 | | 7 Whip Street | 1990's | Craig Carlson | 30-Jun-20 | Building | External brick walls, metal sheet roof, non-asbestos fibre cement sheeting soffits, carport ceiling and hot water system room walls and ceiling | Cement based (1) | N/A | Not present (tested) | Q34076S02 | No asbestos detected | N/A | N/A | N/A | R.11; R.12; R.13 |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | Internal, lounge, dining, bedrooms, sleep out, toilet and kitchen main room masonite walls and ceilings with non-asbestos vinyl sheet flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | Bathroom renovated in 2000 and all non-asbestos construction | N/A | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | No image |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|------------------------------|----------------------|----------|-----------|---------------|------------|---------------|--------------------|--------------|--|----------------------|------------------|--------------------------|-----------------------|----------------------|---------------|---------------------|----------|----------------------------|
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | Kitchen pantry (old stove recess) asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.102 |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | Kitchen foyer area to laundry (old stair foyer) asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.103 |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | Laundry newer construction extension with non-asbestos fibre cement sheeting internal lining and external cladding | N/A | N/A | No asbestos detected | Q34076S11 | No asbestos detected | N/A | N/A | N/A | R.104; R.106 |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | External asbestos cement sheeting soffits and external ceilings. | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.105 |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | External asbestos cement vent pipe for amenities | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.107 |
| Roma | 74 Bowen Street | Dwelling | 28788 | 6RP86310 | 74 Bowen St | 1960's | Craig Carlson | 1-Jul-20 | Building | External sub-floor asbestos cement packing pieces on stumps | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.108 |
| Roma | 9 Beitz Street | Dwelling | 28989 | 29R8693 | 9 Beitz St | 1994 | Craig Carlson | 1-Jul-20 | Building | Internal lounge, kitchen, dining, bedrooms, toilet and hallway construction plasterboard walls and ceilings with non-asbestos flooring | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | 9 Beitz Street | Dwelling | 28989 | 29R8693 | 9 Beitz St | 1994 | Craig Carlson | 1-Jul-20 | Building | Internal laundry and bathrooms non-asbestos fibre cement sheeting walls and plasterboard ceilings | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.87; R.88 |
| Roma | 9 Beitz Street | Dwelling | 28989 | 29R8693 | 9 Beitz St | 1994 | Craig Carlson | 1-Jul-20 | Building | External brick walls, metal sheet roof, non-asbestos fibre cement sheeting soffits and infill panels | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.89 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | Lounge, kitchen including back foyer asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Confirmed | Q34076S126 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.719; R.720 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | Bedrooms (three), centre hall, entry foyer and toilet asbestos cement sheeting walls and ceiling and carpet and non-asbestos vinyl sheet flooring | Cement based (1) | Bonded | Confirmed | Q34076S125 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.721; R.722; R.723 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | Bathroom newly renovated; suspect all asbestos removed and new non-asbestos fibre cement sheeting installed | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.724 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | Sunroom asbestos cement sheeting walls and ceiling | Cement based (1) | Bonded | Presumed | Similar to Q34076S125 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.725 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | Lower level laundry area asbestos cement sheeting (tilux) sink splashback | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.726 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | External asbestos cement sheeting plumbing drain trap formworks at rear for laundry and for toilet (three total) | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.727; R.728 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | External compressed asbestos meter mounting panel at rear | Insulation board (2) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.729 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | External asbestos cement sheeting soffits including verandah ceilings | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.730; R.731 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | External asbestos cement vent pipe | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Medium | R.731 |
| Roma | Northern Road - Bassett Park | Dwelling - Caretaker | 28792 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 18-Aug-20 | Building | External non-asbestos fibre cement sheeting panel above hot water system | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.732 |
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Internal lounge, kitchen, dining, toilet and centre hall asbestos cement sheeting walls and ceilings throughout with non-asbestos vinyl sheet flooring | Cement based (1) | Bonded | Confirmed | Q34076S24 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.141; R.142; R.143; R.145 |
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Internal bedrooms (three) asbestos cement sheeting walls and ceiling and carpet flooring | Cement based (1) | Bonded | Confirmed | Q34076S24; Q34076S25 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.144 |
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Internal bathroom newly renovated and all non-asbestos construction | N/A | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | No image |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|------------------------------|----------------------------------|----------|-----------|--------------------|------------|---------------|--------------------|--------------|---|----------------------|------------------|--------------------------|----------------------|----------------------|---------------|---------------------|----------|---------------------|
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Lower level all concrete block, timber and plasterboard construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Building external asbestos cement sheeting artificial weatherboard walls on upper level | Cement based (1) | Bonded | Confirmed | Q34076S61 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.146; R.147 |
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Building external asbestos cement sheeting soffits and verandah ceilings | Cement based (1) | Bonded | Presumed | Similar to Q34076S24 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.147; R.148 |
| Roma | Northern Road - Bassett Park | Dwelling - Trainer | 28796 | 7RP173059 | 136 McPhie St | 1970's | Craig Carlson | 1-Jul-20 | Building | Building electrical board mounting panel compressed asbestos board | Insulation board (2) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Unsealed bonded (2) | Low | R.149 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | Lounge/kitchen/dining asbestos cement sheeting walls and ceilings with carpet and non-asbestos vinyl sheet flooring | Cement based (1) | Bonded | Confirmed | Q34076S39 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.206 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | Bedrooms (three) and centre hall asbestos cement sheeting walls and ceilings with carpet and non-asbestos vinyl sheet flooring | Cement based (1) | Bonded | Presumed | Similar to Q34076S39 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.207; R.208 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | Toilet asbestos cement sheeting walls and ceiling with non-asbestos vinyl sheet flooring | Cement based (1) | Bonded | Presumed | Similar to Q34076S39 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.209 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | Bathroom asbestos cement sheeting walls and ceiling with ceramic tile flooring on unknown substrate | Cement based (1) | Bonded | Presumed | Similar to Q34076S39 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.210 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | Lower level internal walls showing installation date 2009 | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.211 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | Lower level laundry asbestos cement sheeting sink splashback | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.212 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | External asbestos cement sheeting artificial weatherboard cladding on upper level | Cement based (1) | Bonded | Confirmed | Q34076S40 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.213 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | External asbestos cement sheeting soffits including verandah ceilings | Cement based (1) | Bonded | Presumed | Similar to Q34076S40 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.213 |
| Roma | Saleyards | Dwelling | 60370 | 285WV1474 | 44589 Warrego Hwy | 1970's | Craig Carlson | 4-Jul-20 | Building | External at rear three asbestos cement sheeting drain trap surrounds for plumbing services | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.214 |
| Roma | Roma Quarry | Managers Office | 28679 | 1SP200044 | 3401 Carnarvon Hwy | 1990's | Craig Carlson | 6-Jul-20 | Building | Demountable all timber laminate internal walls and ceiling and metal sheeting external walls and roof | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.215 |
| Roma | Roma Quarry | Smoko and Toilets Building | 28680 | 1SP200044 | 3401 Carnarvon Hwy | 1990's | Craig Carlson | 6-Jul-20 | Building | Demountable all timber laminate and non-asbestos fibre cement sheeting internal walls and ceilings and metal sheeting external walls and roof | Cement based (1) | N/A | Not present (tested) | Q34076S41 | No asbestos detected | N/A | N/A | N/A | R.216; R.217; R.218 |
| Roma | Roma Quarry | Weighbridge Office and Toilets | 28685 | 1SP200044 | 3401 Carnarvon Hwy | Post 2000 | Craig Carlson | 6-Jul-20 | Building | Demountable all metal sandwich panel internal walls and ceiling and metal sheeting external walls and roof | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.219 |
| Roma | Roma Quarry | Workshop | 28687 | 1SP200044 | 3401 Carnarvon Hwy | Post 2000 | Craig Carlson | 6-Jul-20 | Building | Rear stored generator suspected asbestos gaskets - unable to sample or inspect | Fibrous gasket (2) | Friable | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed friable (2) | Low | R.220 |
| Roma | Roma Quarry | Workshop | 28687 | 1SP200044 | 3401 Carnarvon Hwy | Post 2000 | Craig Carlson | 6-Jul-20 | Building | Building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.221 |
| Roma | Roma Saleyards | Compressor Shed | 55420 | 285WV1474 | 44589 Warrego Hwy | 1980's | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.189 |
| Roma | Roma Saleyards | Controllers Shack | 55445 | 285WV1474 | 44589 Warrego Hwy | 2009 | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction with non-asbestos fibre cement sheeting infill panels under glazing | Cement based (1) | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.198 |
| Roma | Roma Saleyards | Generator - Back Yards - Shelter | 55273 | 285WV1474 | 44589 Warrego Hwy | 1980's | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.195 |
| Roma | Roma Saleyards | Loadout Office | 55267 | 285WV1474 | 44589 Warrego Hwy | Post 2000 | Craig Carlson | 4-Jul-20 | Building | Main building all metal sandwich panel sheeting roof, walls and ceiling | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.197 |
| Roma | Roma Saleyards | Machinery Shed | 55265 | 285WV1474 | 44589 Warrego Hwy | 2019 | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.199 |
| Roma | Roma Saleyards | Paint Shed | 55266 | 285WV1474 | 44589 Warrego Hwy | 1980's | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.196 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|-------------------------------|-------------------------------|----------|-----------|-------------------|------------|---------------|--------------------|--------------------------|---|------------------|------------------|--------------------------|-----------------------|----------------------|---------------|---------------------|----------|----------------------------|
| Roma | Roma Saleyards | Pumphouse | 55461 | 285WV1474 | 44589 Warrego Hwy | 2015 | Craig Carlson | 4-Jul-20 | Building | Main building concrete block walls with metal sheeting roof; all equipment asbestos free | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.200 |
| Roma | Roma Saleyards | Roof Shade Structure | 55413 | 285WV1474 | 44589 Warrego Hwy | Post 2000 | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.201 |
| Roma | Roma Saleyards | Roof Structure | 55419 | 285WV1474 | 44589 Warrego Hwy | 1990's | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.202 |
| Roma | Roma Saleyards | Roof Structure | 55457 | 285WV1474 | 44589 Warrego Hwy | 1990's | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.203 |
| Roma | Roma Saleyards | Scales Office (small) | 55434 | 285WV1474 | 44589 Warrego Hwy | 1990's | Craig Carlson | 4-Jul-20 | Building | Internal all non-asbestos fibre cement sheeting walls and ceiling including offices and toilet; external all metal sheeting with non-asbestos fibre cement sheeting soffits | Cement based (1) | N/A | Not present (tested) | Q34076S38 | No asbestos detected | N/A | N/A | N/A | R.190; R.191; R.192; R.193 |
| Roma | Roma Saleyards | Scales Office (large) | 55452 | 285WV1474 | 44589 Warrego Hwy | 2008 | Craig Carlson | 4-Jul-20 | Building | Timber laminate internal walls and ceiling with metal sheeting external walls and roof and non-asbestos fibre cement sheeting soffits | Cement based (1) | N/A | Not present (not tested) | None taken | No asbestos detected | N/A | N/A | N/A | R.194 |
| Roma | Roma Saleyards | Shadecover | 55350 | 285WV1474 | 44589 Warrego Hwy | 1990's | Craig Carlson | 4-Jul-20 | Building | Main building all steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.204; R.205 |
| Roma | Roma Saleyards | Storage Facility | 62642 | 285WV1474 | 44589 Warrego Hwy | Unknown | Craig Carlson | 4-Jul-20 | N/A | Building removed | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Sewerage Treatment Plant | Shady Shed | 60737 | 1RP905205 | 206 Tiffin St | Post 2000 | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.673 |
| Roma | Roma Sewerage Treatment Plant | Storage Shed | 47875 | 1RP905205 | 206 Tiffin St | Post 2000 | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.674 |
| Roma | Roma Sewerage Treatment Plant | STP Site Office | 60740 | 1RP905205 | 206 Tiffin St | Post 2000 | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.671 |
| Roma | Roma Sewerage Treatment Plant | STP Workshop and Storage Shed | 60739 | 1RP905205 | 206 Tiffin St | Post 2000 | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.675 |
| Roma | Roma Sewerage Treatment Plant | Primary Tanks (three) | Unknown | 1RP905205 | 206 Tiffin St | Post 2000 | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All concrete tanks with steel and PVC pipes | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.672 |
| Roma | Roma Sewerage Treatment Plant | Chlorine Shed | Unknown | 1RP905205 | 206 Tiffin St | Post 2000 | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.676 |
| Roma | Roma SPS1 | Well Structure | Unknown | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | Asbestos cement vent pipe sections (two) on top of well structure | Cement based (1) | Bonded | Confirmed | Q34076S119 | Chrysotile (1) | Fair (2) | Sealed bonded (1) | Low | R.677; R.678 |
| Roma | Roma SPS1 | Amenities Building | Unknown | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | Internal throughout masonite walls with asbestos cement sheeting ceiling | Cement based (1) | Bonded | Confirmed | Q34076S120 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.679 |
| Roma | Roma SPS1 | Amenities Building | Unknown | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | Internal asbestos cement sheeting (tilux) lining in shower recess | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.680 |
| Roma | Roma SPS1 | Amenities Building | Unknown | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | Building external asbestos cement sheeting soffits | Cement based (1) | Bonded | Presumed | Similar to Q34076S120 | Chrysotile (1) | Good (1) | Sealed bonded (1) | Very low | R.681 |
| Roma | Roma SPS1 | Amenities Building | Unknown | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | Building external asbestos cement sheeting vent pipe | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Fair (2) | Unsealed bonded (2) | Low | R.682 |
| Roma | Roma SPS1 | Generator Cover | Unknown | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.684 |
| Roma | Roma SPS1 | Storage and Equipment Shed | 63293 | 2RP91085 | 6A Major St | 1970's | Craig Carlson | 14-Aug-20 | Sewerage Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.683 |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|------------------------------|--|----------|--------------|--------------------|------------------|---------------|--------------------|-----------------------|---|------------------|------------------|----------------------|------------|--------------------------------------|---------------|---------------------|----------|---------------------|
| Roma | Roma Bore 02 | Bore 02 Treatment Building | 60674 | 1RP107295 | 108 Corfe Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Water Treatment Plant | Treatment building all concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.685 |
| Roma | Roma Bore 02 | Bore 02 Treatment Building | 60674 | 1RP107295 | 108 Corfe Rd | Post 2000 | Craig Carlson | 14-Aug-20 | Water Treatment Plant | Surface ground redundant asbestos cement sheeting pipe section on ground at west fence | Cement based (1) | Bonded | Presumed | None taken | Chrysotile (1) | Poor (3) | Unsealed bonded (2) | Medium | R.686 |
| Roma | Roma Bore 03 | Bore 03 Treatment Building | 60412 | 11R86120 | 10-12 Whip St | 1970's | Craig Carlson | 14-Aug-20 | Water Treatment Plant | Treatment building brick walls with metal sheeting roof and asbestos cement sheeting soffits; bore equipment all asbestos free | Cement based (1) | Bonded | Confirmed | Q34076S121 | Chrysotile; amosite; crocidolite (3) | Fair (2) | Sealed bonded (1) | Medium | R.687; R.688; R.689 |
| Roma | Roma Bore 09 | Bore 09 Treatment Building | 60681 | 1RP152652 | 150 Currey St | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Treatment building all concrete block and metal sheeting construction; bore equipment all asbestos free | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.700 |
| Roma | Roma Bore 11 | Bore 11 Treatment Building | 60524 | 3RP157707 | Warrego Hwy | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Treatment building all concrete block and metal sheeting construction; bore equipment all asbestos free | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.704 |
| Roma | Roma Bore 12 | Bore 12 Treatment Building | 60684 | 2RP170339 | 12-20 Bungil St | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Treatment building all concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.705 |
| Roma | Roma Bore 15 | Bore 15 Treatment Building | 60675 | 1WV1938 | Warrego Hwy | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Treatment building all concrete block and metal sheeting construction; bore equipment all asbestos free | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.703 |
| Roma | Roma Bore 17 | Bore 17 Treatment Building | 60678 | 1SP118789 | 328-330 Currey St | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Treatment building all concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.706 |
| Roma | Roma Bore 18 | Large Shed 6x3 - Equipment and Spares | 63188 | Road Reserve | Bungeworgorai Lane | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.701 |
| Roma | Roma Bore 18 | Small Shed 3x3 - Electronics and Switchboard | 63187 | Road Reserve | Bungeworgorai Lane | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.702 |
| Roma | Roma Bore 19 | Pumphouse | 76997 | 14SP300970 | 25 Airport Dr | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.707 |
| Roma | Roma Campbell Park Reservoir | Shed | 42543 | 2RP131502 | 44426 Warrego Hwy | 1960's | Craig Carlson | 15-Aug-20 | Reservoir | Main tank all concrete; disused asbestos cement pipe collar on surface ground | Cement based (1) | Bonded | Confirmed | Q34076S124 | Chrysotile (1) | Poor (3) | Unsealed bonded (2) | Medium | R.708 |
| Roma | Roma Campbell Park Reservoir | Tank/Reservoir | Unknown | 2RP131502 | 44426 Warrego Hwy | 1960's | Craig Carlson | 15-Aug-20 | Reservoir | All concrete walls, floor and ceiling | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.709 |
| Roma | Roma Miscamble Booster | Pumphouse | 76799 | 8RP128363 | 105 Miscamble St | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.710 |
| Roma | Water Tower Booster | Building | 74992 | 7SP222875 | 68-72 Bowen St | Unable to locate | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Unable to locate; refer Facilities Corporate for Water Tower buildings | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Water Tower Hill Booster | Building | 74993 | 7SP222875 | 68-72 Bowen St | Unable to locate | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Unable to locate; refer Facilities Corporate for Water Tower buildings | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |
| Roma | Roma Water Tower Reservoir | Ground level Reservoir Treatment Building | 55592 | 7SP222875 | 68-72 Bowen St | Post 2000 | Craig Carlson | 15-Aug-20 | Reservoir | Treatment building all concrete block and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.711 |
| Roma | Roma Northern Rd Booster | Pumphouse | 55698 | 1RP173063 | 136 McPhie St | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.714 |
| Roma | Roma Potable Water Facility | Booster Pump Building | 56508 | 185SP154287 | 192-230 Currey St | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | Concrete block external walls with non-asbestos fibre cement sheeting internal walls and metal sandwich panel ceiling and soffits | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.715; R.716; R.717 |
| Roma | Roma Reardons Booster | Pumphouse | 55783 | Road Reserve | Roma Downs Rd | Post 2000 | Craig Carlson | 15-Aug-20 | Water Treatment Plant | All steel and metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.718 |
| Roma | Roma Refuse Tip | Weighbridge Donga | 28613 | 241WAL53170 | 231-249 Short St | Post 2000 | Craig Carlson | 30-Jun-20 | Building | Internal all timber construction; external metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.01 |
| Roma | Roma Refuse Tip | Lunch Hut | Unknown | Unknown | 231-249 Short St | Post 2000 | Craig Carlson | 30-Jun-20 | Building | Internal all timber construction; external metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.02 |
| Roma | Roma Refuse Tip | Office | Unknown | Unknown | 231-249 Short St | Post 2000 | Craig Carlson | 30-Jun-20 | Building | Internal all timber construction; external metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | No image |

| Town | Facility | Building | Asset No | Lot Plan | Address | Build Date | Auditor | Date of Inspection | ACM Location | Use of ACM / Component | ACM Material | Friable / Bonded | ACM Status | Sample # | ACM Type | ACM Condition | ACM Treatment | ACM Risk | Photo # |
|------|-----------------|---------------------------------|----------|----------|------------------|------------|---------------|--------------------|--------------|---|--------------|------------------|----------------------|------------|----------------------|---------------|---------------|----------|---------|
| Roma | Roma Refuse Tip | Workshop and adjacent buildings | Unknown | Unknown | 231-249 Short St | 1990's | Craig Carlson | 30-Jun-20 | Building | Buildings all metal sheeting construction | N/A | N/A | No asbestos detected | None taken | No asbestos detected | N/A | N/A | N/A | R.03 |